



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0998/2020/NS
DATE : 22-Dec-20
WIP : 63656

VEHICLE IS NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

5 days ok jb 12 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR THAM TIEN HOONG FIDELIS
ADDRESS : BLK 165 BISHAN STREET 13
#19-274
SINGAPORE 570165
TELEPHONE : HP +65 97703227
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100454499-04
VEHICLE NO : **SJZ 1406 B**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI S
MODEL YEAR : 29/2/2016
ENGINE NO : CVN 002251
CHASSIS NO : WAUZZZF48GA024009
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Dec-20
PLACE OF ACCIDENT : ORCHARD REDEZVOUS HOTEL CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 1406 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	\$ 1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	
6	Added labour charge	\$ 1,280.00	\$ 800.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 6,562.00	\$ 3,342.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 1406 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,111.00	
2	FRONT BUMPER FIXING PARTS		\$ 282.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 70.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 208.00	
5	FRONT BUMPER AIR GUIDE - RH		\$ 62.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 361.00	
7	FRONT BUMPER GUIDE SECTION - RH		\$ 37.00	
8	FRONT FENDER - RH		\$ 758.00	\$ 606.00
9	FRONT FENDER ATTACHMENT PARTS		\$ 200.00	
10	FRONT FENDER CLOSING ELEMENT - RH		\$ 49.00	
11	FRONT FENDER BRACKET - RH		\$ 35.00	
12	DEFORMATION ELEMENT BRACKET - RH		\$ 49.00	
13	FRONT FENDER BRACE - RH		\$ 117.00	
14	WHEEL HOUSING LINER - RH		\$ 239.00	
15	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 90.00	
16	WHEEL SPOILER		\$ 73.00	
17	WHEEL SPOILER TRIM		\$ 36.00	
18	STONE CHIP GUARD		\$ 50.00	
19	TOP FENDER LEDGE COVER - UPPER		\$ 31.00	\$ 24.40
20	TOP FENDER LEDGE COVER - LOWER		\$ 23.00	\$ 17.68
SUB-TOTAL SPARE PARTS		:	\$ 4,881.00	\$ 648.08

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 1406 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 648.08
21	LED HEADLIGHT - RH	\$	7,693.00	\$ 6,154.40
22	LIFT CYLINDER - RH	\$	208.00	
23	FRONT ALUMINIUMRIM - RH	\$	589.00	
24	Added parts - see attached	\$	82.00	\$ 64.80
25	SUNDRIES	\$	200.00	\$ 15.36
TOTAL SPARE PARTS		:	\$ 13,653.00	\$ 6,882.64
TOTAL LABOUR CHARGES		:	\$ 6,562.00	\$ 3,342.00
GRAND TOTAL		:	\$ 20,215.00	\$ 10,224.64

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
bl-06/02/21

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0998/2020/NS 18-Jan-21 CHANG 1 of 1 SJZ 1406 B AUDI A4 SEDAN 1.4 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Labours</u>				
1	TO DISMANTLE RHS FRONT DOOR PANEL S/N TRIM, REMOVE AND REINSTALL SIDE MIRROR ASSY TO FACILITATE DOOR RESPRAY	\$ 280.00	\$	250.00
2	TO RESPRAY RHS FRONT DOOR.	\$ 1,000.00	\$	550.00
<u>Parts</u>				
1	HEADLIGHT COMPENSATING PIECE - UPPER	\$ 40.00	\$	31.84
2	HEADLIGHT COMPENSATING PIECE - LOWER	\$ 42.00	\$	32.96
GRAND TOTAL		\$ 1,362.00	\$	864.80

For Premium Automobiles Pte Ltd

 Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LAOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT