

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 877L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	IONIQVC COVER-RR BUMPER	CRACKED	459.40	459.40
1	IONIQVC LAMP ASSY-REAR FO	CRACKED	201.50	201.50
1	IONIQV2-4 MOULDING ASSY-R	DEFORMED	451.25	451.25
1	IONIQVC CAP-RR HOOK	MISSING	98.80	98.80
1	IONIQVC MOULDING-REAR BUM	DEFORMED	155.00	155.00
1	IONIQVC COVER-RR BPR UNDE	MISSING	225.00	225.00
10	HYUNDAI BUMPER COVER CLIP	NOT NECESSARY	22.00	-
1	IONIQVC BEAM-RR BUMPER	NOT NECESSARY	394.80	-
1	IONIQVC STAY-RR BUMPER RH	BENT	138.10	138.10
1	IONIQVC STAY-RR BUMPER LH	NOT NECESSARY	138.10	-
1	IONIQ COVER INNER BUMPER	TORN	108.00	108.00
1	IONIQ ANTENNA ASSY	CRACKED	40.50	40.50
	LESS 20% DISCOUNT		-486.49	-375.51
			1,945.96	1,502.04
	NETT ITEMS			
1	HYUNDAI REVERSE SENSOR AS (N)	NOT WORKING	180.00	180.00
1	NO PLATE (S) (N)	CRACKED	25.00	25.00
	LESS 10% DISCOUNT		-20.50	-20.50
			184.50	184.50
	SPECIAL NETT ITEMS			
1	IONIQVC PROTECTOR MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	320.00
	SPRAYPAINT CHARGE.		300.00	200.00
	REMOVE AND REFIX REVERSE SENSOR.		80.00	30.00
			780.00	550.00
	GRAND TOTAL		2,960.46	2,286.54

Report Ref No. NS/INC20014359/T1qd3e2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED)		2,286.54
---	--	----------

Report Ref No. NS/INC20014359/T1qd3e2

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.