



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12352/Ms Kok Lan Choo Reg No/Reg Date SMT2709S / 03/04/202 Date In/Mileage / 21019 Chassis No KNAF5416ML5060347 Engine No G4FGKH739818 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	23/12/2020/ 12:52	QUD	247 / DonBong	26230		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2000.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 400 x 4							1600
FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER,							
REPAIR RH FRONT DOOR PANEL, REPAIR LH FRONT FENDER							100.00
E PNT88000							
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER							80.00
TO FACILITATE REPAIR WORK							
M SUNDRY							60.00
TOP UP A/CON GAS AND CHECK A/CON SYSTEM							
E PNT88000							
REMOVE AND INSTALL PARKING ASSIST 350 x 5							2100.00
E PNT98000							1750
PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER,							
RH FRONT FENDER, RH FRONT DOOR, LH FRONT FENDER							
AND AFFECTED PORTION							40 120.00
M SUNDRY							30.00
APPLY BODY SEALANT							
A 54900099							40 120.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
M SUNDRY							120.00
PERFORM RUST PREVENTION							
A 10028901							50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							20 50.00
SUPPLY FRONT NUMBER PLATE WITH FRAME							
M SUNDRY							
SUNDRIES				1.00	675.00	20.00	540.00
M CARRIER ASSY-FRONT END MODULE / BR				1.00	497.00	20.00	397.60
M BEAM COMPLETE-FR BUMPER				1.00	26.00	23.00	20.02
M COOLANT (4L) / PIC				1.00	28.00	20.00	22.40
M GUARD-AIR, LH / X				1.00	28.00	20.00	22.40
M GUARD-AIR, RH / CKY							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12352/Ms Kok Lan Choo Reg No/Reg Date SMT2709S / 03/04/202 Date In/Mileage / 21019 Chassis No KNAF5416ML5060347 Engine No G4FGKH739818 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	23/12/2020/ 12:52	QUD	247 / DonBong	26230			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	CONDENSER ASSY-COOLER				1.00	687.00	20.00	549.60
M	RADIATOR ASSY				1.00	646.00	20.00	516.80
M	BLOWER ASSY				1.00	656.00	20.00	524.80
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M	STIFFNER-FR BPR LWR				1.00	114.00	20.00	91.20
M	ABSORBER-FRONT BUMPER ENERGY				1.00	84.00	20.00	67.20
M	AIR DUCT-FR BUMPER,LH				1.00	14.00	20.00	11.20
M	AIR DUCT-FR BUMPER,RH				1.00	14.00	20.00	11.20
M	LAMP ASSY-SIDE REPEATER,LH				1.00	143.00	20.00	114.40
M	LAMP ASSY-SIDE REPEATER,RH				1.00	143.00	20.00	114.40
M	MOULDING-FRONT BUMPER,LH				1.00	216.00	20.00	172.80
M	MOULDING-FRONT BUMPER,RH				1.00	216.00	20.00	172.80
M	GARNISH-RADIATOR GRILLE				1.00	38.00	20.00	30.40
M	GRILLE ASSY-RADIATOR				1.00	328.00	20.00	262.40
M	COVER-FR BUMPER				1.00	633.00	20.00	506.40
M	CAP-FRONT HOOK				1.00	9.00	20.00	7.20
M	GRILLE-FRONT BUMPER				1.00	485.00	20.00	388.00
M	COVER-FR BUMPER FOG LAMP,LH				1.00	15.00	20.00	12.00
M	COVER-FR BUMPER FOG LAMP,RH				1.00	15.00	20.00	12.00
M	RETAINER-BUMPER SIDE MTG				2.00	1.00	20.00	1.60
M	LAMP ASSY-FRONT FOG,LH				1.00	303.00	20.00	242.40
M	LAMP ASSY-FRONT FOG,RH				1.00	303.00	20.00	242.40
M	ULTRASONIC SENSOR ASSY-P.A.S				1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-P.A.S				1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-P.A.S				1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-P.A.S				1.00	163.00	20.00	130.40
M	ORNAMENT-KIA NO.115				1.00	32.00	20.00	25.60
M	PANEL-FENDER,RH				1.00	430.00	20.00	344.00
M	HINGE ASSY-HOOD,RH				1.00	43.00	20.00	34.40
M	HINGE ASSY-HOOD,LH				1.00	43.00	20.00	34.40
M	PANEL ASSY-HOOD				1.00	1502.00	20.00	1201.60
M	PAD-HOOD INSULATING				1.00	156.00	20.00	124.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or by cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing.





CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV12352/Ms Kok Lan Choo
	Reg No/Reg Date	SMT2709S / 03/04/202
	Date In/Mileage	/ 21019
	Chassis No	KNAF5416ML5060347
	Engine No	G4FGKH739818
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	BAU GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	23/12/2020/ 12:52	QUD	247 / DonBong	26230			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LATCH ASSY-HOOD	X			1.00	103.00	20.00	82.40
M	HORN ASSY-LOW PITCH	- BR			1.00	74.00	20.00	59.20

## Estimate

SURVEYOR NAME: Steve CLKK 23/12/20, 2.07pm

SURVEYOR SIGNATURE: OO-NH AIL

DATE: EXCIS - ?

REMARKS: PIP

6 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

Acknowledged by Repairer  
Signature:

Authorized signatory and company stamp

7% GST on 12346.82

Nett 12,346.82

Total Payable 13,211.10

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing