



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	LCV12352/Ms Kok Lan Choo SMT2709S / 03/04/202 / 21019 KNAF5416ML5060347 G4FGKH739818 KIA/CERATO 1.6 A GT LINE H171 B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LAX00000	Credit	23/12/2020/ 12:52	QUD	247 / DonBong	26230				2000.00
Description of Goods / Services									
E PNT88000									1600
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 490 x 6 FRONT BONNET, FRONT BUMPER FACE, RH FRONT FENDER, REPAIR RH FRONT DOOR PANEL, REPAIR LH FRONT FENDER									100.00
E PNT88000									80.00
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK									60.00
M SUNDRY									2100.00
TOP UP A/CON GAS AND CHECK A/CON SYSTEM									
E PNT88000									1750
REMOVE AND INSTALL PARKING ASSIST									
E PNT98000									40
PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, RH FRONT DOOR, LH FRONT FENDER AND AFFECTED PORTION									120.00
M SUNDRY									30.00
APPLY BODY SEALANT									
A 54900099									40
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									120.00
M SUNDRY									120.00
PERFORM RUST PREVENTION									
A 10028901									50.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST									
M SUNDRY									20
SUPPLY FRONT NUMBER PLATE WITH FRAME									50.00
M SUNDRY									540.00
SUNDRIES									
M CARRIER ASSY-FRONT END MODULE						1.00	675.00	20.00	397.60
M BEAM COMPLETE-FR BUMPER						1.00	497.00	20.00	20.02
M COOLANT (4L)						1.00	26.00	23.00	22.40
M GUARD-AIR,LH						1.00	28.00	20.00	22.40
M GUARD-AIR,RH						1.00	28.00	20.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12352/Ms Kok Lan Choo Reg No/Reg Date SMT2709S / 03/04/202 Date In/Mileage / 21019 Chassis No KNAF5416ML5060347 Engine No G4FGKH739818 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim BAU GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	23/12/2020/ 12:52	QUD	247 / DonBong	26230			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M CONDENSER ASSY-COOLER	BT	1.00	687.00	20.00	549.60			
M RADIATOR ASSY	X NNI	1.00	646.00	20.00	516.80			
M BLOWER ASSY	X NNI	1.00	656.00	20.00	524.80			
M BRACKET-FR BUMPER UPR SIDE MTG	X NNI	1.00	22.00	20.00	17.60			
M BRACKET-FR BUMPER UPR SIDE MTG	X NNI	1.00	22.00	20.00	17.60			
M STIFFNER-FR BPR LWR	X NNI	1.00	114.00	20.00	91.20			
M ABSORBER-FRONT BUMPER ENERGY	OR	1.00	84.00	20.00	67.20			
M AIR DUCT-FR BUMPER, LH	X NNI	1.00	14.00	20.00	11.20			
M AIR DUCT-FR BUMPER, RH	X NNI	1.00	14.00	20.00	11.20			
M LAMP ASSY-SIDE REPEATER, LH	X NNI	1.00	143.00	20.00	114.40			
M LAMP ASSY-SIDE REPEATER, RH	BT	1.00	143.00	20.00	114.40			
M MOULDING-FRONT BUMPER, LH	OR	1.00	216.00	20.00	172.80			
M MOULDING-FRONT BUMPER, RH	OR	1.00	216.00	20.00	172.80			
M GARNISH-RADIATOR GRILLE	OR	1.00	38.00	20.00	30.40			
M GRILLE ASSY-RADIATOR	OR	1.00	328.00	20.00	262.40			
M COVER-FR BUMPER	OR	1.00	633.00	20.00	506.40			
M CAP-FRONT HOOK	MIS	1.00	9.00	20.00	7.20			
M GRILLE-FRONT BUMPER	X NNI broken	1.00	485.00	20.00	388.00			
M COVER-FR BUMPER FOG LAMP, LH	X NNI	1.00	15.00	20.00	12.00			
M COVER-FR BUMPER FOG LAMP, RH	X NNI	1.00	15.00	20.00	12.00			
M RETAINER-BUMPER SIDE MTG	OR	2.00	1.00	20.00	1.60			
M LAMP ASSY-FRONT FOG, LH	X NNI	1.00	303.00	20.00	242.40			
M LAMP ASSY-FRONT FOG, RH	X NNI	1.00	303.00	20.00	242.40			
M ULTRASONIC SENSOR ASSY-P.A.S	X NNI	1.00	163.00	20.00	130.40			
M ULTRASONIC SENSOR ASSY-P.A.S	X NNI	1.00	163.00	20.00	130.40			
M ULTRASONIC SENSOR ASSY-P.A.S	X NNI	1.00	163.00	20.00	130.40			
M ULTRASONIC SENSOR ASSY-P.A.S	X NNI	1.00	163.00	20.00	130.40			
M ORNAMENT-KIA NO.115	OR	1.00	32.00	20.00	25.60			
M PANEL-FENDER, RH	OR	1.00	430.00	20.00	344.00			
M HINGE ASSY-HOOD, RH	BT	1.00	43.00	20.00	34.40			
M HINGE ASSY-HOOD, LH	BT	1.00	43.00	20.00	34.40			
M PANEL ASSY-HOOD	OR	1.00	1502.00	20.00	1201.60			
M PAD-HOOD INSULATING	CRU	1.00	156.00	20.00	124.80			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12352/Ms Kok Lan Choo Reg No/Reg Date SMT2709S / 03/04/202 Date In/Mileage / 21019 Chassis No KNAF5416ML5060347 Engine No G4FGKH739818 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	23/12/2020/ 12:52	QUD	247 / DonBong	26230			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LATCH ASSY-HOOD	X	NAI		1.00	103.00	20.00	82.40
M	HORN ASSY-LOW PITCH	-	BR		1.00	74.00	20.00	59.20

Estimate

SURVEYOR NAME: Steve CLKK 23/12/20, 2.00pm

SURVEYOR SIGNATURE: 00-NH AIL

DATE: EXCIS - ?

REMARKS: PIP
My RL 01
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis and legal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer
Signature:

Authorized signatory and company stamp

	Nett	12,346.82
7% GST on	12346.82	864.28
Total Payable		13,211.10

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.