

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014368/KGA3Q2
Date: 05/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SKH434J	Insured Vehicle No :	SLU318G
Date of Loss:	20/12/2020	Nature of Claim:	TP
		Claim No:	4539674252SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH434J		
Make & Model:	MASERATI QUATTROPORTE, 4.7 Sport GT S (A)	Engine No:	M139S154126
Reg. Date:	30/12/2011 (Man. Year: 2010)	Chassis No:	ZAMKK39C000049808
Colour:	Dark Blue	Odometer:	153528 km
Engine Capacity:	4691 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/35Z R20	Rear Tyre Size:	295/30Z R20
Front Left Side:	Pirelli 3 mm	Rear Left Side:	Pirelli 3 mm
Front Right Side:	Pirelli 3 mm	Rear Right Side:	Pirelli 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,840.94	14,240.47	12,600.47	46.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,570.00	1,630.00	2,940.00	64.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,410.94	15,870.47	15,540.47	49.47
Approved Total (Overridden) (S\$)		12,700.00		

Nett Amount (S\$)	31,410.94	12,700.00	18,710.94	59.57
		+ Loss of Use (6.0 x S\$150.00/day) (S\$)	900.00	
		+ Doc/Search Fee (S\$)	7.45	
		Nett Liability (S\$)	13,607.45	

INSPECTION

Date of Assignment: 23/12/2020

Date Inspected: 30/12/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Lim Yew Boo Spray Paint Co (HQ)
 NO. 176 SIN MING DRIVE #03-05, SIN MING IND EST
 Singapore 575645

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	5,163.00 FS	*5,163.00 FS
2	1		*FRONT BUMPER SPONGE	Cracked	231.60 FS	*231.60 FS
3	1		*FRONT BUMPER RETAINER /RH	Distorted	82.01 FS	*82.01 FS
4	1		*FRONT HEADLAMP ASSY /RH	Cut	9,163.00 FS	*8,500.00 FS
5	1		*FRONT HEADLAMP ASSY /LH	Serviceable	9,163.00 FS	*- FS
6	1		*FRONT FENDER /RH	Repair	2,115.37 FS	*- FS
7	1		*FRONT FENDER INNER SHIELD/RH	Serviceable	275.10 FS	*- FS
8	8		*FRONT FENDER INNER SHIELD CLIP /RH	Not Necessary	32.80 FS	*- FS
9	1		*FRONT BUMPER EMBLEM	Necessary	263.86 FS	*263.86 FS
10	1		*FRONT SENSOR	Serviceable	351.20 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	26,840.94	14,240.47
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION	New	150.00	30.00
2	TO REMOVE TYRE ENABLE TO REPAIR RIM & FIX SAME	New	150.00	0.00
3	TO APPLY RUST PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	0.00
4	TO CHECK COMPUTERISED WHEEL ALIGNMENT	New	150.00	0.00
5	TO REPAIR PANEL BEAT ,RE-STRAIGHTEN ON RIGHT FRONT AFFECTED DOOR ,RIGHT INNER HEADLAMP BRACKET TO REMOVE RIGHT TYRE TO ENABLE REPLACEMENT OF HEADLAMP & LABOUR TO REPLACE ABOVE PARTS	New	2,000.00	600.00
6	TO PUTTY ,PRIMER & SPRAY PAINT ON AFFECTED FRONT BONNET ,FRT BUMPER ,FRT SENSOR ,RIGHT FRONT FENDER ,RIGHT FRONT AFFECTED DOOR & RIGHT SIDE SILL USING 2K REARLESCENT PAINT	New	2,000.00	1,000.00
Gross Labour Cost (S\$)			4,570.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >