

Faster
memoryPrecision
touchpadFaster
wirelessGigabit
Ethernet

M YEW BOO SPRAY PAINT CO.

10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
No. : 64534177 Fax No. : 64593724
ail : limyewboo@singnet.com.sg
site : www.limyewboo.com.sg
s. Reg. No. : 200514/00L

ASIA PACIFIC INSURANCE PTE LTD
HENTON WAY #07-16
RTIS BUILDING SINGAPORE 079120

tion : Motor Claim Department
act : 64191000 Fax No. : 64193727 Claims Dept

8ms 1000th - 25.3.21

Not Authorised
11 Sep @ 12.30pm
Paying After Paint

Estimate : TP21/008

5 days

Date : 01/01/2021
Vehicle Num. : SKH 434J
Make/Model : MASERATI QUATTRO SPORT GTS-2010
Chassis/Eng# : ZAMKK39C000049808/M139S154126
Accident Date : 20/12/2020
Claim No. : CC4/AIG20014368/ga3
Reference : LYB/SKH434J/aig/TP/SL
Policy No. :

Quantity	Particular	Unit Price	Amount S\$
----------	------------	------------	------------

1 SPECIAL NETT ITEMS :
1 FRONT BUMPER
1 FRONT BUMPER SPONGE
1 FRONT BUMPER RETAINER/RH
1 FRONT HEADLAMP ASSY/RH 8500
1 FRONT HEADLAMP ASSY/LH
1 FRONT FENDER/RH
1 FRONT FENDER INNER SHIELD/RH
1 FRONT FENDER INNER SHIELD CLIP/RH
1 FRONT FENDER EMBLEM bumper
1 FRONT SENSOR

Buc	5,163.00	✓
cm	231.60	✓
at	82.01	✓
br	9,163.00	✓
sn	9,163.00	X
n	2,115.37	X
sn	275.10	X
4.10	32.80	X
nn	263.86	✓
sn	351.20	X
	26,840.94	

Special Nett Total S\$:

LABOUR :
TO FOCUS HEADLAMP & CHECK HEADLAMP WIRING FUNCTION

150.00 30/

TO REMOVE TYRE ENABLE TO REPAIR RIM & FIX SAME

nn 150.00 X

TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS

nn 120.00 X

TO CHECK COMPUTERISED WHEEL ALIGNMENT

nn 150.00 X

TO REPAIR, PANEL BEAT, RE-STRAIGHTEN ON RIGHT FRONT
AFFECTED DOOR, RIGHT INNER HEADLAMP BRACKET. TO REMOVE

CONTINUE / ...

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

YEW BOO SPRAY PAINT CO.

SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
534177 Fax No. : 64593724
yewboo@singnet.com.sg
www.limyewboo.com.sg
No. : 200514/00L

PACIFIC INSURANCE PTE LTD
1 WAY #07-16
BUILDING SINGAPORE 079120

Motor Claim Department
91000 Fax No. : 64193727 Claims Dept

Estimate : TP21/008

Date : 01/01/2021
Vehicle Num. : SKH 434J
Make/Model : MASERATI QUATTRO SPORT GTS-2010
Chassis/Eng# : ZAMKK39C000049808/M139S154126
Accident Date : 20/12/2020
Claim No. : CC4/AIG20014368/ga3
Reference : LYB/SKH434J/aig/TP/SL
Policy No. :

Quantity	Particular	Unit Price	Amount S\$
	RIGHT TYRE TO ENABLE REPLACEMENT OF HEADLAMP & LABOUR TO REPLACE ABOVE PARTS		2,000.00 <i>60d</i>
	TO PUTTY, PRIMER & SPRAY PAINT ON AFFECTED FRONT BONNET, FRONT BUMPER, FRONT SENSOR, RIGHT FRONT FENDER, RIGHT FRONT AFFECTED DOOR & RIGHT SIDE SILL USING 2K PEARLESCENT PAINT		<i>100d</i> 2,000.00
	Labour Total S\$:		4,570.00



E. & O.E.

Total S\$: 31,410.94

=====

YEW BOO SPRAY PAINT CO.