



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Khairul Azmeel Bin Kahar Blk 810A Choa Chu Kang Avenue 7 #03-501 Singapore 681810 Contact No Mobile: 98339530	Cust No/Name /Khairul Azmeel Bin Kahar Reg No/Reg Date SLW5634A / 22/02/201 Date In/Mileage / 0 Chassis No KNAFZ411MJ5764432 Engine No G4FGJH694654 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	23/12/2020/ 14:40		442 / CocoLu	26256			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT SUPPORT PANEL, REPAIR FRT FENDER RH								400 1200.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH								350 700.00
M SUNDRY FRT NUMBER PLATE WITH FRAME								50.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR								60.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY Sundry								20.00
M COVER-FR BUMPER					1.00	633.00	00.00	633.00
M MOULDING-FRT BPR LICENSE PLATE					1.00	18.00	00.00	18.00
M GRILLE ASSY-RADIATOR					1.00	328.00	00.00	328.00
M GARNISH-RADIATOR GRILLE,UPR					1.00	54.00	00.00	54.00
M MOULDING-FRONT BUMPER A/INTAKE					1.00	91.00	00.00	91.00
M DUCT ASSY-AIR CURTAIN,RH					1.00	6.00	00.00	6.00
M AIR DUCT-FR BUMPER,RH					1.00	33.00	00.00	33.00
M LAMP ASSY-FRONT FOG,RH					1.00	241.00	00.00	241.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	00.00	84.00
M RAIL ASSY-FR BUMPER					1.00	496.00	00.00	496.00
M BRACKET-FR BUMPER SIDE MTG,RH					1.00	13.00	00.00	13.00
M ULTRASONIC SENSOR ASSY-P.A.S					1.00	177.00	00.00	177.00
M LAMP ASSY-HEAD,RH					1.00	2209.00	00.00	2209.00
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	00.00	675.00

Estimate

00
BR
BR
? X NN
(clone) ? X NN
? X NN
? X NN
? X NN
OT
? X NN
? X NN
? X NN
? X NN

Stere (LKK)
00 - Nm AL
Excess - ?

Stere (CLKK) 00-NM AL
EXCESS-?

Confirm & accepted by 23/12/20
3:00pm

3 days
P/P

7% GST on Net 7,238.00 506.66

Total Payable 7,744.66

LKK Auto Consultants hence notify

the Receiver of the following:
Authorized signatory and company stamp

- Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
- Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque.
- You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repairs requiring the removal of the windscreen.

Acknowledged by Repairer