



AIG - OD CLAIM
SURVEY: 23/12/20
LKK - STEVE

VEHICLE NO : SLW 5634A

MODEL : KIA/CERATO K3 1.6 A SX

WIP : 26256

Material	:	\$	<u>3,229.60</u>
Labour	:	\$	<u>1,150.00</u>
Sub-Total	:	\$	<u>4,379.60</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>4,079.60</u>
GST 7%	:	\$	<u>285.57</u>
Grand Total	:	\$	<u>4,365.17</u>
Finalise By/Date : <u>Larry on 06/01/21</u>			



REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING



SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS + 2 days (P.H.)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Khairul Azmeel Bin Kahar Reg No/Reg Date SLW5634A / 22/02/2018 Date In/Mileage 23/12/2020/ 21264 Chassis/Package KNAFZ411MJ5764432 /FS1F Engine No G4FGJH694654 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim MST METAL STREAM / WK SATURN BLACK
23/12/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	06/01/2021/ 09:33	BLC	884 / Lauro Songcuan	26256

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER				400.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER				350.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60.00 ✓
A 90000001 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)				50.00 ✓
E PNT88000 REMOVE & INSTALL FRT AIRDAM → <i>supp</i>				80.00 ✗
M SUNDRY APPLY SEALANT FOR FRONT AIRDAM → <i>supp</i>				40.00 ✗
X EXC EXCESS FOR OWN DAMAGE CLAIM				-300.00
X COVER-FR BUMPER ✓	1.00	633.00	20.00	506.40 ✓
X MOULDING-FRT BPR LICENSE PLATE ✓	1.00	18.00	20.00	14.40 ✓
X GRILLE ASSY-RADIATOR ✓	1.00	328.00	20.00	262.40 ✓
X ABSORBER-FRONT BUMPER ENERGY ✓	1.00	84.00	20.00	67.20 ✓
X RAIL ASSY-FR BUMPER ?	1.00	496.00	20.00	396.80 ✓
X LAMP ASSY-HEAD,RH ✓	1.00	2209.00	20.00	1767.20 ✓
X WIRING HARNESS-FR BUMPER → <i>supp</i>	1.00	237.00	20.00	189.60 ✗
X ORNAMENT-KIA NO.115 → <i>supp</i>	1.00	32.00	20.00	25.60 ✗
Z TEXT OD CLAIM - AIG SURVEY: STEVE (LKK) 23/12/2020 DOA: 23/12/2020 (03 DAYS) <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	3,229.60	Nett	4,079.60
Labour	1,040.00	7% GST on	285.57
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	4,365.17
Sundry/Others	-240.00		
Total(w/o GST)	4,079.60		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SLW 5634 A

Materials

- 1 Wiring Harness- FR Bumper
- 2 Ornament- KIA No. 115

Cost \$

237.00

32.00

269.00

20% Discount

53.80

215.20

Labour

- 1 Remove & Install Front Airdam
- 2 Apply Sealant for Front Airdam

80.00

40.00

120.00

Labour & Materials

335.20

7% GST

23.46

Total

358.66

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SLW56344

\$80 ✓


WIP: 26256

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Remove & mgt for base door (405)	? / SUPP		NR	Steve 3/1/21
2		? / SUPP			
3	Wiring for air door (405)	? (SUPP)			Steve 3/1/21
4		? / SUPP			
5	Rail Assy - FRT Bumper	? / SUPP		✓ DO 3/1/21	86530 A7600
6	Wiring Assy - FRT	? / SUPP		✓ RR 3/1/21	91821 A7020
7		? / SUPP			
8	Air door sealant \$40	? / SUPP		✓ NR	Steve 5/1/21
9	Rta loga RA	? / SUPP		✓ NR	
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	30/12/20	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: CeratoSURVEYOR: Steve



HOME

Online



CERATO/FORTE../2018/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



CLU



BCM



SJB



PSM

10/10

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
SMK	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0235

VCI Ver.

02.48

ECU Ver.


M-E-K-01-00-0176

OS Ver.

Android 9

 Fault Code Searching

Rescan Erase All DTC Go to DTC Save



System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
SMK	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0235	VCI Ver.	02.48
ECU Ver.	M-E-K-01-00-0176	OS Ver.	Android 9