



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Khairul Azmeel Bin Kahar  Blk 810A Choa Chu Kang Avenue 7 #03-501 Singapore 681810  Contact No Mobile: 98339530	Cust No/Name	/Khairul Azmeel Bin Kahar
	Reg No/Reg Date	SLW5634A / 22/02/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MJ5764432
	Engine No	G4FGJH694654
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	23/12/2020/ 14:40		442 / CocoLu	26256			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200.00
RENEW FRT BUMPER, FRT SUPPORT PANEL, REPAIR FRT FENDER RH								
E PNT98000								700.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								20.00
Sundry								
M COVER-FR BUMPER					1.00	633.00	00.00	633.00
M MOULDING-FRT BPR LICENSE PLATE					1.00	18.00	00.00	18.00
M GRILLE ASSY-RADIATOR					1.00	328.00	00.00	328.00
M GARNISH-RADIATOR GRILLE,UPR					1.00	54.00	00.00	54.00
M MOULDING-FRONT BUMPER A/INTAKE					1.00	91.00	00.00	91.00
M DUCT ASSY-AIR CURTAIN,RH					1.00	6.00	00.00	6.00
M AIR DUCT-FR BUMPER,RH					1.00	33.00	00.00	33.00
M LAMP ASSY-FRONT FOG,RH					1.00	241.00	00.00	241.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	00.00	84.00
M RAIL ASSY-FR BUMPER					1.00	496.00	00.00	496.00
M BRACKET-FR BUMPER SIDE MTG,RH					1.00	13.00	00.00	13.00
M ULTRASONIC SENSOR ASSY-P.A.S					1.00	177.00	00.00	177.00
M LAMP ASSY-HEAD,RH					1.00	2209.00	00.00	2209.00
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	00.00	675.00

Confirm &amp; accepted by

7% GST on      **Nett**      **7,238.00**  
                              **7238.00**      **506.66**

**Total Payable      7,744.66**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.