

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 20 Jan 2021

Preliminary Advice

Insured Vehicle No	: SKG5145R		
TP Vehicle No	: SME9971H	Accident Date	: 19/12/2020
Make	: VOLVO XC40	Assignment Date	: 23/12/2020
Date of Inspection	: 11/01/2021	Est. Duration of Repair	: 6
Inspection At	: WEARNES AUTOMOTIVE PTE LTD (LENG KEE) 28 LENG KEE ROAD SINGAPORE 159105		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,075.70
Revised Amount	:S\$	7,018.50
Check Items (Estimated)	:S\$	10,657.20
Total	:S\$	17,675.70
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :