

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO20014383/AUtd3e2	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	Date:	26/04/2022	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBB 4097K	Veh. Inspected	SLR 3503J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2003766/GPL	Excess (\$)	0.00	
	Assign From	MELVIN YE YONG KANG	Assign Date	23/12/2020	
2.	. Vehicle Particulars & Condition				
	Make & Model	HONDA STEP WAGON	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	RP31019398	Colour	WHITE	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
	L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
	R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
	L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/12/2020	Inspection Date	24/12/2020	
	Survey held at	RYDER AUTO WORKSHOP LLP			
		2 Kaki Bukit Ave 2# 02-19 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days				