

12/12/2020

REF: CS/SMO20014383/d3

Special Instruction:

ASS. REC. BY:

SURVEY BY:

ASSIGNMENT (Office)

From (Person): MELVIN YE YONG of SMO

Date/Time: 23/12/2020@4.53PM

Estimated Cost:

Bill to:

OD ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLR 3503J

Insured: GBB 4097K

at Workshop m/s RYDER AUTO

Tel: 6741 8277

of 2 Kaki Bukit Ave 2 #02-19 AUTOHUB

Policy No:

Claim No: CMTD2003766/GPI

Sum Insured:

Excess:

D.O.A. 22/12/2020

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 5PM@23/12/2020

Person Contacted: ORSON

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	Repairer agreed to survey on 24/12/2020
	SLR 3503J-X
	GBB 4097K-X