

ESTIMATE OF REPAIR

RP31019398

Veh# : SLR3503J

Model:

Honda Spada

Accident Date : 22/12/2020

T.P. Sompo

(4/1/2016)

Location : SLE TOWARDS BKE

Denise

3P:

GBB4097K(SOMPO)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear n/s bumper <i>Dehnd</i>	652.34	✓	-
2	1pc	Rear n/s bumper garnish <i>New</i>	185	X	-
3	1pc	Rear n/s bumper chrome <i>New</i>		62.40	✓
4	10pcs	Rear bumper clips <i>New</i>		30.00	✓
5	2pcs	Rear bumper o/s & n/s reflector <i>3 NP</i>		X	-
6	2pcs	Rear bumper o/s & n/s reflector garnish <i>3 NP</i>		X	-
7	2pcs	Rear bumper o/s & n/s retainer <i>N/s New</i>	170.00	85	-
8	1 set	Rear reverse sensor <i>2 Dented</i>		380.00	240 (SW)
9	1pc	Rear reverse camera <i>New M.C.</i>		680.00	X
10	1pc	Rear end panel <i>Repis</i>		X	-
11	1pc	Rear end panel inner trim <i>Dehnd</i>	286.91	✓	-
12	4pcs	Rear end panel inner trim clips <i>New</i>		16.00	✓
13	2pcs	Rear o/s & n/s tail-lamp <i>N/s cracked</i>	2,290.34	6/10	-
14	2pcs	Rear o/s & n/s tail-lamp panel <i>Repis</i>		X	-
15	1pc	Rear n/s boot cover <i>Dented</i>	1,812.45	✓	-
16	1pc	Rear n/s boot cover inner trim <i>cracked</i>	452.70	30/20	-
17	8pcs	Rear n/s boot cover inner trim clips <i>New</i>		33.00	✓
18	2pcs	Rear n/s boot cover hinges <i>New</i>		X	-
19	1pc	Rear n/s boot cover chrome (n/s) <i>New</i>		100.00	✓
20	1pc	Rear n/s boot cover garnish (n/s) <i>Dehnd</i>	405.00	✓	-
21	1pc	Rear n/s boot cover chrome (middle) <i>New</i>		150.00	✓
22	1pc	Rear n/s windscreen <i>Shattered</i>	1,885.00	1295	-
23	1pc	Rear n/s windscreen sealant <i>New</i>		40.00	✓
24	1pc	Rear n/s windscreen moulding <i>3 NP</i>	131.17	✓	-
25	1pc	Rear n/s windscreen chrome <i>Dented</i>		256.50	✓
26	1pc	Rear boot cover frame <i>Dented</i>	2,775.60	X	-
27	1pc	Rear boot cover chrome (middle) <i>New</i>	507.78	29340	-
28	1pc	Rear boot cover garnish (o/s) (TOP) <i>Dehnd</i>	542.08	✓	-
29	1pc	Rear boot cover chrome (o/s) <i>3 NP</i>		100.00	✓
30	1pc	Rear boot cover stepwgn sticker <i>3 NP</i>		30.00	✓
31	1pc	Rear o/s windscreen <i>3 NP</i>		X	-
32	1pc	Rear o/s windscreen sealant <i>3 NP</i>		40.00	X
33	1pc	Rear o/s windscreen moulding <i>3 NP</i>	151.17	X	-
34	1pc	Rear boot cover weatherstrip <i>cut</i>	334.39	✓	-
35	1pc	Rear boot cover emblem <i>3 NP</i>	69.65	✓	-
36	1pc	Rear boot cover 'Stepwgn' emblem <i>3 NP</i>	97.63	✓	-
37	1pc	Rear boot cover 'Spada' emblem <i>3 NP</i>	71.50	✓	-
38	1pc	Rear boot frame <i>Repaired</i>		X	-

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SLR3503J

Model:

Honda Spada
(4/1/2016)

Accident Date : 22/12/2020

3P:

GBB4097K(SOMPO)

Location : SLE TOWARDS BKE

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear n/s boot lock <i>Pangd</i>	430.00	✓	-
2	1pc	Rear end panel inne trim garnish (bellow) <i>Delid</i>	240.60	✓	-
3	1pc	Rear o/s boot cover chrome <i>He n</i>	120.00	X	-
4	1pc	Front bumper chrome moulding (lower) <i>He n</i>	-	120.00	X
5	1pc	Rear keyless module <i>He n</i>	350.00	X	-
6	1pc	Rear o/s door weather strip <i>He n</i>	270.60	X	-
7	1pc	Rear wiper motor <i>Pangd</i>	465.60	-	-
8	1pc	Rear boot cover garnish (o/s) (Lower) <i>Delid</i>	562.08	-	-
9	1pc	Rear n/s windscreen solar film <i>Neu</i>	-	150.00	✓
Sub-Total:			2,438.88	270.00	0.00
			20%	0%	10%
After Less %:			1,951.10	270.00	0.00
Total:			2,221.10		
After Less 20%:			1,776.88		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

1263.6
1010.88

SN: 150



8778 1999
24 hr accident call

Mobil 1



Supplementary: 1160.88