

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

SUPPLEMENTARY ESTIMATE OF REPAIR

Veh# : SLR3503J

Model:

Honda Spada

(4/1/2016)

Accident Date : 22/12/2020

3P:

GBB4097K(SOMPO)

Location : SLE TOWARDS BKE

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1pc	Rear n/s boot lock <i>Pangd</i>	430.00	✓	-
2	1pc	Rear end panel inne trim garnish (bellow) <i>Delid</i>	240.60	✓	-
3	1pc	Rear o/s boot cover chrome <i>He n</i>	120.00	X	-
4	1pc	Front bumper chrome moulding (lower) <i>He n</i>	-	120.00	X
5	1pc	Rear keyless module <i>He n</i>	350.00	X	-
6	1pc	Rear o/s door weather strip <i>He n</i>	270.60	X	-
7	1pc	Rear wiper motor <i>Pangd</i>	465.60	-	-
8	1pc	Rear boot cover garnish (o/s) (Lower) <i>Delid</i>	562.08	-	-
9	1pc	Rear n/s windscreen solar film <i>Neu</i>	-	150.00	✓
Sub-Total:			2,438.88	270.00	0.00
			20%	0%	10%
After Less %:			1,951.10	270.00	0.00
Total:			2,221.10		
After Less 20%:			1,776.88		

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)

1263.6

1010.88

SN: 150



8778 1999
24 hr accident call

Mobil 1



Supplementary : 1160.88