

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Lee Chen Sin
CLAIM DEPARTMENT
DID : 66547520
FAX :

Date : 22/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000085

Accident Date : 17/12/2020

Vehicle No : SMT-3768-P

Make & Model : KIA CERATO L 1.6 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
List Item			
	RESTORE		
1	REAR BOOTLID X NN	355.40	
1	REAR LAMP OUTER RH ? XSVL	575.20 ✓	
1	REAR BUMPER CM ✓	55.00 ✓	
10	REAR BUMPER CLIPS CM ✓	45.50 ✓	
1	REAR BUMPER SIDE BRACKET RH REX ✓	54.30	
1	REAR BUMPER INNER BRACKET RH ? XSVL	285.60 ✓	
1	REAR BUMPER SIGNAL LAMP RH CM ✓	55.10 ✓	
1	REAR BUMPER SIGNAL LAMP COVER RH CM ✓	284.70 ✓	
1	REAR BUMPER LOWER GARNISH CM ✓		
		<u>1301.10</u>	

Date : 22/12/2020

To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000085 Accident Date : 17/12/2020

Vehicle No : SMT-3768-P Make & Model : KIA CERATO L 1.6 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER REINFORCEMENT <i>con</i>	355.20	<i>355.20</i>
3	REAR BUMPER REINFORCEMENT BRACKET RH <i>? x sul</i>	82.60	
1	REAR BUMPER REINFORCEMENT ARM RH <i>2 x sul</i>	75.80	
1	REAR END PANEL <i>repair</i>	455.20	
	Sub Total	2679.60	
	Discount 10% On Parts	(267.96)	
	Special Nett Item		
1	REVERSE SENSOR <i>? x sul</i>	220.00	
1	END PANEL SEALANT <i>x m</i>	40.00	
1	REAR BUMPER ADV STICKER <i>na</i>	500.00	<i>450</i>
		<i>1656.30</i>	
		<i>10%</i>	
		<u><i>1490.67</i></u>	

Date : 22/12/2020

To : **INDIA INTERNATIONAL INSURANCE PTE LTD**
ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D20MTRENT000085 Accident Date : 17/12/2020

Vehicle No : SMT-3768-P Make & Model : KIA CERATO L 1.6 (A)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BOOTLID ADV STICKER	NEC 400.00 350	350 350
	Sub Total	1160.00	800 800
Labour & Misc			
	LABOUR TO CARRY OUT REAR REPAIR	800.00	500 /
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	/
	TO SPRAY PAINTING ON REAR AFFECTED AREA	700.00	400 600 /
	SPRAY RUST PROOF ON AFFECTED AREA	40.00	X AN
	TO DETACH & RENEW REVERSE SENSOR	60.00	/
			1195 /

Date : 22/12/2020
 To : INDIA INTERNATIONAL INSURANCE PTE LTD
ESTIMATION
 Attn : Motor Claim Department FAX :

Owner : ETHOZ Group Ltd
 : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Certificate No : D20MTRENT000085 Accident Date : 17/12/2020
 Vehicle No : SMT-3768-P Make & Model : KIA CERATO L 1.6 (A)

ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	1635.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1490.67
 800.00
 1195.00
 3485.67
 5 days

Remarks: 5,206.64

5 days / Part by Part

SUB TOTAL
GST 7.0 % 364.46
TOTAL 5,571.10

Surveyor's name: Rasul - Hp 9006068
 Principal's name: ETHOZ Group Ltd
 Survey Date & Time: 23/12/2020 01440