

ASS. REC. BY:

REF:

CS/MSG20014395/Rtd3

6849

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKU 2741Rat Workshop m/s XINYA AUTOof (102, BUKIT MELAKA LN3 #01-75Insured: MSIA

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 48K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKU 2741R Yr Regn: 2015 / JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: CITROEN C4 PICASSO 1.6 c.c. 1560Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 091141 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF 7309H C8 FJ 659158Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 22/12/2020Survey held at XINYADes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 29/12/2020

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 16klump sum \$4350 (red: 3737.10 + 4620)

Date/Time, File Pass to?

1) 1/13

Date/Time, File Return to?

2) _____



: Preli. Report



: Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

: Interview (\$ _____)



: Tech. Invs (\$ _____)



: Weekend (\$ _____)



: _____

Survey Fee: _____

Transportation: _____

S + RS. SI _____

Photos _____

Others _____

TOTAL _____

Report Format: TPLump Sum / L.P.A. (\$ 4350)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 23/12/2020

Address : MR THONG KAM SENG
BLK 426 JURONG WEST AVENUE 1
#03-338
SINGAPORE 640426

Reference : TP 1266/12/20
Vehicle No : SKU 2741R
Make/Model : CITREON C4
Insurance Co. : AIG

RE : QUOTATION TO SKU 2741R FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

		QTY		AMT \$	
1)	REAR BUMPER <i>repair</i>	1	\$	822.00	<i>XR</i>
2)	REAR BUMPER REFLECTOR <i>XSU</i>	2	\$	406.00	<i>X</i>
3)	REAR ENFORCEMENT <i>X SU</i>	1	\$	425.00	<i>X</i>
4)	TAIL GATE <i>CM</i>	1	\$	2,185.00	
5)	TAIL GATE LOWER GARNISH <i>CM</i>	1	\$	520.00	
6)	TAIL LAMP <i>CM</i>	2	\$	680.00	
7)	CITREON LOGO <i>NE</i>	1	\$	108.00	
8)	CITREON EMBLEM <i>NE</i>	1	\$	108.00	
9)	"C4" EMBLEM <i>NE</i>	1	\$	82.00	
10)	"e HDI" EMBLEM <i>NE</i>	1	\$	86.00	
11)	"PICASSO" EMBLEM <i>NE</i>	1	\$	112.00	
12)	BUMPER CLIPS <i>NE</i>	10	\$	100.00	

3981.00

10%

3582.90

LIST PRICE TOTAL
LESS DISCOUNT 10%
LIST PRICE TOTAL AFTER LESS
NETT PRICE TOTAL

\$ 5,634.00
\$ 563.40
\$ 5,070.60

\$0.00

TOTAL PARTS COST

\$5,070.60

LABOUR AND MISCELLANEOUS CHARGES

- TO REMOVE & REPLACE REAR BUMPER, TAILGATE, TAILLAMPS AND PANEL BEAT & ALIGN.
- TO PUTTY & SPRAY PAINT REAR BUMPER, TAILGATE (OUTER & INNER) AND OTHER AFFECTED AREA.

\$ 1,000.00
(5 DAYS)

\$ 800.00
(4 PANELS)

3) TO CHECK & RECTIFY WIRING.

1030

\$ ~~80.00~~ 30

4) TUFF KOTE

\$ 220.00 X

LABOUR TOTAL

\$ 2,100.00

TOTAL ESTIMATED REPAIR COST

\$ ~~7,170.60~~

2 087.10

3582.90

35.00

1030.00

706.50

1201.00

5474.40

20%

4379.52

48-4,350

4 days

Rene

Hp 9001068

4 days

4s

29/12/2020 @ 1020

Revy after repair

XINYA AUTO SERVICES PTE LTD

BLK 1002 BUKIT MERAH LANE 3, UNIT # 01 -75, SINGAPORE 159719
E-mail : xinyaauto@singnet.com.sg

Date : 23/12/2020

Address : MR THONG KAM SENG
BLK 426 JURONG WEST AVENUE 1
#03-338
SINGAPORE 640426

Reference : TP 1266/12/20
Vehicle No : SKU 2741R
Make/Model : CITREON C4
Insurance Co. : AIG

RE : SUPPLYMENTARY TO SKU 2741R FOR THIRD PARTY CLAIMS.

PARTS REQUIRED

	<u>QTY</u>	<u>COST</u>	<u>AMT \$</u>
1) TAIL GATE INNER BOARD GARNISH / OR	1		\$785.00

LIST PRICE TOTAL

LESS DISCOUNT 10%

LIST PRICE TOTAL AFTER LESS

\$ 785.00

\$ 78.50

\$ 706.50

2) WINDSCREEN SEALANT

1

\$50.00

NETT PRICE TOTAL

\$50.00

TOTAL PARTS COST

\$756.50

LABOUR AND MISCELLANEOUS CHARGES

1) TO REMOVE & REFIT WINDSCREEN AND CHECK FOR WATER TIGHT

\$160.00 120

LABOUR TOTAL

\$ -

TOTAL ESTIMATED REPAIR COST

\$ 916.60

Steve
30/12/20, 4.00pm

P - 706.50
L - 120.00