

ASS. REC. BY: Sun Pin

REF:

CS/CT120014399/G+d3ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGC 1593A Yr Regn: 21/01/2016Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Peugeot. 5008. c.c. 1560Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 103491 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF30E9HD8FS212614Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_Tyre Size: F: 215 / 60 R16R: 215 / 60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FirenzaFront R/Bal. 6 mmRear R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 20/12/2020D.O.I. 24/12/2020Survey held at Auto Insure.Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☐ U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV: 50,000PV: 39,525NV: 10,475Part by Part \$5,153.76. 6days  
(Red: 916.24; 15%)before due to camera sport.  
No after paint ~ inform by Bryan just submit. Any question  
will then answer by then

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

S + RS. \$ \_\_\_\_\_

☐ : Interview (\$ \_\_\_\_\_)

Photos

☐ : Tech. Invs (\$ \_\_\_\_\_)

Others

☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

Rep. Format: \_\_\_\_\_

Lump Sum / L.B. / P. \_\_\_\_\_





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	21/12/2020 14:39 (SGT)
Date of Accident	20/12/2020 13:00 (SGT)
Exact Location of Accident	Near 550a Segar Rd, Singapore
Additional Location Information	along bukit panjang ring near blk 515 jelapang road
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGC1593A
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ALLIMRAN BIN LOMRI
NRIC No	SXXXX843B
Email Address	ALLIMARAN.LOMRI76@GMAIL.COM
Mobile Phone No	(Phone) +65-88769426
Alternative Phone No	+65-88769426

#### VEHICLE PARTICULARS

Manufacturer	Peugeot
Model	5008
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire

#### INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMHCSNW00008152000
Cover Note Number	-

#### DRIVER

Name of Driver	ALLIMRAN BIN LOMRI
NRIC No	SXXXX843B
Date Of Birth	30/06/1976
Occupation	Outdoor





## Date Of Driving Pass

13/05/1995

Driving experience

25 YEARS AND 7 MONTHS

Gender

Male

Mobile Number

(Phone) +65-88769426

Alt. Phone Number

+65-88769426

Email Address

ALLIMARAN.LOMRI76@GMAIL.COM

Address

BLK 473 SEGAR ROAD #02-312

Address complement

-

Postcode

670473

Is the driver the policyholder?

Yes

If No, Relationship of the Driver with the Insured

-

Does Driver Own Other Vehicles?

No

Vehicle Registration Number of Other Vehicle Owned by Driver

-

Insurance Company of Other Vehicle Owned by Driver

-

## GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Collision - Head to Rear

Weather Conditions

Clear

Road Surface

Dry

## OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No

Number of vehicles involved in the accident

2

Was anybody injured in the Accident?

No

Was any injured conveyed to hospital by ambulance?

-

Was any other material or property damaged?

Yes

Number of Passengers (Including Driver)

0

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No

## DETAILS OF POLICE ACTION

Was the accident reported to the police?

No

Was notice of intended Prosecution given?

No

If yes, against whom?

-

## CIRCUMSTANCES OF ACCIDENT

ON 20DEC2020 AT AROUND 1300HRS . I WAS TRAVELLING ALONG BUKIT PANJANG RING ROAD NEAR JELAPANG RD . VEHICLE B STOPPED AT THE ROAD SIDE , I THAN COLLIDED INTO VEHICLE B . I TRY TO AVOID THE COLLISION BUT INEVITABLE .

## ATTACHMENT(S)

Are accident photos available for attachment?

Yes

Was there any video captured by Car Camera?

No

Was there any audio recorded?

No

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHB6242Z

Vehicle Manufacturer

-

Vehicle Model

-

Vehicle Variant

-

Vehicle Colour

-

Vehicle Category

Taxi

Name of Driver

XIAO WEIGUO

NRIC No

SXXXX868F

Contact Number

(Phone) +65-91074698

Address

-



Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

### SKETCH PLAN

**SKETCH PLAN**

Along Buhi Road

On Highway at about 100m, I was travelling along Buhi Road, and

with stopped at the road side

the individual onto vehicle B. I try to avoid the person but

unavoidable

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: *[Signature]*

Date & Time:

Driver's Signature: *[Signature]*

If driver is not the policyholder:

Date & Time:

Receiving Centre/Personnel's Signature: *[Signature]*

Name:

NAIC/MIN No:



SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. The Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to release of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
  - (i) understand, acknowledge, agree and consent that:
    - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"). The Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
      - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
      - (ii) investigating the accident and/or my claims;
      - (iii) carrying out and/or dealing with my instructions or responding to any inquiries by me;
      - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices in writing, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
      - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively, the "Purposes").
    - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
    - (c) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
    - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
    - (e) the information so collected under (d) above may be shared / disclosed:
      - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud;
      - (ii) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
      - (iii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time: 31/12/2018  
10:58 AM

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name  
NRIC/IN ID



**Auto Insure Pte. Ltd**  
**6 Marsiling Lane**  
**739145**



**Insurer Reference: M1288**  
**Repairer Reference: SGC1593A**  
**Date calculated: 22/12/2020 3:58 PM**

**Full Report**  
**Registration: SGC1593A**  
**Printed: 22/12/2020 3:59 PM**

### Summary Information

#### Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Heng Cheng Chung	Currency:	SGD
Claim Reference:	M1288	Date of Incident:	20/12/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

#### Vehicle

Manufacturer:	PEUGEOT
Model:	5008 (0A-0E)
Sub Model:	BASE MODEL
Model Sheet Number:	11 83 01
Registration:	SGC1593A
VIN number:	VF30E9HD8FS212614
Odometer:	103491

#### Model Specs

FROM 05/2015	AUTO AIR CON	AIR CON 2 BLOWER	USB SOCKET
DEAD LOCKS	FRT/RR ELECT WINDOWS	ELEC CHILD LOCKING	ELECT FOLDING MIRROR
PHONE SYS BLUETOOTH	RADIO SYSTEM NG4	S-WHEEL RADIO CONT	RECEPTION IMPROVED
BI-TUNER	FOG LAMPS	REAR PARKING SYSTEM	ADDITIONAL HEATING
CLOTH TRIM	HEIGHT ADJ PASS SEAT	7 SEATS	ACOUSTICS IMPROVED
RAIN SENSOR	TRIM TRAMONTANE	S/BELT W/WARNING DEV	MODULAR PASS SEAT
S-WDW ROLLER BLIND	ENTRANCE LAMPS	WDW MOULDING CHROME	INNER MIRROR/SENSOR
REARVIEW CAMERA	1.6 LTR 82/84KW	BATTERY 12V 70AH	6-SPEED CONTROLLED
LEATH S-WHEEL 3 SPK	HEAD-UP DISPLAY	CRUISE CONTROL	TYRES 215/55 HR 16
DUST ATMOSPHERE	SPARE WHEEL	ENGINE FAN 140W	SPARE WHEEL WINCH
TYRE PRESSURE SENSOR	CATALYST MORE 50PPM	HEAD AIRBAG	FRONT SIDE AIRBAG
PANORAMA SUNROOF	EMISSION STD EURO 5	STOP-START SYSTEM	STARTER MTR CLASS 5
PAINTED MOULDINGS	TWO COAT METALLIC		



## Vehicle Condition


### Vehicle Status

Pre-Accident Damage:  
Date of Inspection:

### Damage Areas

All

Underbody

☐  
☐


## Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
71.EVVA	RENEW L/F INNER WING PANEL REINFORCEMENT			
74.ERCA)	R + R FRONT BUMPER		20.0	84.00
74.ERDA)	RENEW FRONT BUMPER		9.0	37.80
NO NUMBER	R + R FRONT UPPER BUMPER CARRIER		17.0	71.40
NO NUMBER	R + R FRONT LOWER BUMPER CARRIER		2.0	8.40
62.E4KA)	R + R L/HEADLAMP		2.0	8.40
	(FRONT BUMPER REMOVED)		1.0	4.20
62.E4KA)	R + R R/HEADLAMP		1.0	4.20
	(FRONT BUMPER REMOVED)			
78.E1WA)	R + R LEFT FRONT WING		5.0	21.00
NO NUMBER	R + R L/F WING BRACKET		1.0	4.20
79.E0YA	R + R BONNET		4.0	16.80
79.E0WA)	RENEW BONNET (REMOVED)		1.0	4.20
79.E0FS)	RENEW L/BONNET HINGE		1.0	4.20
79.E0FS)	RENEW R/BONNET HINGE		1.0	4.20
NO NUMBER	R + R BONNET LOCK		1.0	4.20
NO NUMBER	R + R BONNET STAY		1.0	4.20
78.E6OA)	R + R BONNET OPENER CABLE		1.0	4.20
78.E1GA	R + R COWL GRILLE		1.0	4.20
78.E6WA)	R + R COWL COLLECTOR		2.0	8.40
NO NUMBER	R + R LOWER INSTRUMENT PANEL TRIM		2.0	8.40
NO NUMBER	R + R FUSE BOX		4.0	16.80
56.E0KA	R + R BATTERY		3.0	12.60
74.EP4A)	R + R FRONT LOWER AIR GUIDE		3.0	12.60
NO NUMBER	R + R LEFT FRONT IMPACT DAMPER		2.0	8.40
96.E0VA	R + R LOWER ENGINE PROTECTION		1.0	4.20
62.E1KS	ADD: ADJUST HEADLAMPS		4.0	16.80
62.E1KS	ALIGN FRONT FOG LAMPS		3.0	12.60
			3.0	12.60



**Labour Cost**  
**Panel / Mechanical Labour**  
**Total of Labour**

Hrs	WU	
9.50	95.0	399.00
		399.00

**Paint**

Paint Work

**SYSTEM AZT**

Code	Description - TWO COAT METALLIC	Time Basis 10 WU/h	WU	Price SGD
	BONNET NEW PART PAINTING		16.0	
	L/F FILL PANEL REINF SURFACE PAINT		4.0	
	FRONT BUMPER NEW PART PAINT K1R		15.0	
	L/F WING NEW PART PAINT K1R		5.0	

**Paint Material Per Part**

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	45.41
1165	L/F FILL PANEL REINF SURFACE PAINT	2.99
0281	FRONT BUMPER NEW PART PAINT K1R	78.72
0741	L/F WING NEW PART PAINT K1R	15.74

**Labour Cost - Paint**

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint				
Preparation Main Work Metal			40.0	
Preparation Comp. Work Plastic		1.10	11.0	46.20
<b>Total</b>		0.50	5.0	21.00
	10 WU/h	5.60	56.0	235.20

**Material Cost - Paint**

	Price SGD
New Part Painting	45.41
New Part Painting - Plastic K1R	94.46
Surface-/Blend Paint	2.99
Material-constant Metal	18.10
Material-constant Plastic	9.00
<b>Total</b>	169.96

**Spare Parts**

Code	Description	Part Number	Part Source	prices as at 2001-01-01	Price SGD
0471 ✓	BONNET	7901 R2	Original		830.00
0501	BONNET CONTROL	7937 V0	Original	2xnn	60.00
0481 ✓	BONNET INSULATION	7979 L2	Original	1xcr4	150.00
0493	BONNET LOCK	7934 E6	Original	X	50.00
0496	BONNET STAY	7927 74	Original	X	35.00
1397	COWL COLLECTOR	8251 FX	Original	X	150.00
0479	CTR BONNET MOULDING	7966 39	Original	X	135.00
0303	FR LWR BUMPER GRILLE	98 054 992 80	Original	X	120.00
0281 ✓	FRONT BUMPER	16 112 036 80	Original	X	610.00
0341 ✓	FRONT LOWER CARRIER	98 054 348 80	Original	X	180.00
0288	FRT BUMPER BRKT KIT	16 112 056 80	Original	X	60.00



Code	Description	Part Number	Part Source	Price SGD
0306	FRT BUMPER GRILLE	98 056 749 80	Original 22	100.00
0309	FRT BUMPER PROTECT	98 054 955 XT	Original 2 7mm	75.00
0313	FRT GRILLE MOULDING	16 112 042 80	Original CRA	200.00
0340	FRT UPP BUMPER CARR	98 054 349 80	Original 2 CM	135.00
0307	FR UPP BUMPER GRILLE	98 054 968 80	Original 2 CM	220.00
9659	FUSE BOX	6500 CC	Original 2 CM	90.00
9661	FUSE BOX	98 070 285 80	Original BT	275.00
0475	L/BONNET HINGE	7912 F8	Original BT	50.00
0477	L/BONNET MOULDING	7966 38	Original 2 Xnn	45.00
0291	L/F BUMPER COVER	98 054 941 80	Original X nn	90.00
1165	L/F FILL PANEL REINF	98 088 510 80	Original CRU	350.00
0637	L/F FOG LAMP	96 854 252 80	Original 2 CM	90.00
0321	L/F IMPACT DAMPER	SEE GUIDE NO. 0327	Original 2 Xnn	180.00
0839	L/F WHEELHOUSE COVER	7136 JT	Original CRU	90.00
0741	L/F WING	7840 Y7	Original end	380.00
0749	L/F WING BRACKET FRT	7119 QC	Original PER M.S	80.00
0627	L/HEADLAMP ADJUSTER	16 108 035 80	Original CRU	180.00
0287	L/LOCK	98 056 747 80	Original 2 Xnn	50.00
0561	LEFT HEADLAMP ASSY	98 055 056 80	Original CRU	770.00
9663	MODULE BOX COVER	6500 CA	Original 2 Xnn	50.00
0476	R/BONNET HINGE	7913 48	Original BT	50.00
0478	R/BONNET MOULDING	7966 37	Original 2 Xnn	45.00
Savings				0.00
Subtotal				5,975.00
Total				5,975.00

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

Repair day - 6 days

P/P

before pull photo

Excess - \$1,250

Rev - OD

Sun Pin (LH)

24/12/2020

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_



## Final Calculation

	SGD	SGD
<b>Parts</b>		
<b>Total Parts</b>	5,975.00	<b>5,975.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 95.0 WU X 42.00 SGD/h		
<b>Total of Labour</b>	348.60 399.00	<b>399.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 56.0 WU X 42.00 SGD/h		
Material Cost	235.20	
<b>Total Paint Including Material</b>	169.96	<b>405.16</b>
<b>Repair Cost Excludes GST</b>		<b>6,779.16</b>
GST (+7.00%)		<b>474.54</b>
<b>Repair Cost Included GST</b>		<b>7,253.70</b>
<b>Deductions (Excludes GST)</b>		
Deduction For Excess		
<b>Total Of Deductions (Excludes GST)</b>	-1,250.00	<b>-1,250.00</b>
<b>Grand Total Excludes GST</b>		<b>5,529.16</b>
GST (+7.00%)		<b>387.04</b>
<b>Grand Total Included GST</b>		<b>5,916.20</b>

### Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

### Assessment Note

No assessment notes entered.