

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20014400/QPA3Q2  
**Date:** 25/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900129643
<b>Claimant Vehicle No :</b>	EQ650A	<b>Insured Vehicle No :</b>	SKZ588D
Date of Loss:	28/11/2020	Nature of Claim:	TP
		Claim No:	6050442124SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>EQ650A</b>	Engine No:	101025
Make & Model:	PORSCHE CAYENNE, 3.0 (A)	Chassis No:	WP1ZZZ92ZDLA30052
Reg. Date:	25/03/2013 (Man. Year: 2012)	Odometer:	178182 km
Colour:	Silver		
Engine Capacity:	2967 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	265/50 R19	Rear Tyre Size:	265/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	22/12/2020	
Date Inspected:	23/12/2020 Inspected At:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate Singapore 677981
Estimated Period of Repair:	4.0 days	

**Adjuster:** OI SUN PIN

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Scratched	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR LH TAILLAMP	Crumpled	0.00 F	*- F
5	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
6	1		*REAR LH FENDER PROTECTOR	Scratched	0.00 F	*- F
				<b>Total Parts (\$\$)</b>	<b>0.00</b>	<b>0.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >