

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20014402/T1TD3E2
Date: 19/01/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MS009390
Claimant Vehicle No : SHA6992Y Insured Vehicle No : GBG2911Y
Date of Loss: 22/12/2020 Nature of Claim: TP Claim No: M2006338

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA6992Y
Make & Model: TOYOTA PRIUS HYBRID, 1.8 (A) Engine No: 2ZRS065687
Reg. Date: 28/09/2017 (Man. Year: 2017) Chassis No: JTDKB3FU603564863
Colour: Blue Odometer: 387964 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,878.85	1,539.85	3,339.00	68.44
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,350.00	990.00	360.00	26.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,239.85	2,540.85	3,699.00	59.28
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	6,239.85	2,000.00	4,239.85	67.95
+ GST 7.00/7.00% (S\$)	436.79	140.00	296.79	67.95
Nett Amount (S\$)	6,676.64	2,140.00	4,536.64	67.95

INSPECTION

Date of Assignment: 23/12/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected: 23/12/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2021)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA6992Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER ASSY	Deformed	499.90 FL	-	*499.90 FL
2	1		*FRONT BUMPER BRACKET RH	Not Necessary	77.00 FL	-	*- FL
3	1		*FRONT FENDER RH	Bent	945.30 FL	-	*945.30 FL
4	1		*FRONT FENDER SHIELD RH	Deformed	198.50 FL	-	*198.50 FL
5	1		*HEAD LAMP ASSY RH	Not Necessary	3,455.00 FL	-	*- FL
6	1		*FRT DAY LIGHT ASSY RH	Not Necessary	920.00 FL	-	*- FL
7	1		*FRT FENDER EMBLEM	Necessary	86.50 FL	-	*86.50 FL
8	1		*FRT WHHEL COVER RH	Deformed	189.60 FL	-	*189.60 FL
9	1		*FRT FENDER ADVERTISEMENT	Necessary	100.00 FS	-	*100.00 FS
					Sub Total (S\$)	6,471.80	2,019.80
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,592.95	479.95
					Total Parts (S\$)	4,878.85	1,539.85

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	480.00
2	SPRAY PAINTING	New	500.00	400.00
3	CHECK WIRING	New	60.00	30.00
4	RESET WHEEL ALIGNMENT	New	90.00	80.00
Gross Labour Cost (S\$)			1,350.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >