

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288
 ATTN: Motor Claim Department

FAX: 68804739

Estimate No: ES2091043
 Date: 23 Dec 2020

Veh Reg No: SMH9315L
 Make/Model: TOYOTA TOYOTA
 ALPHARD 2.5CVT
 ELEGANCE S/R

WS Ref: TP AIG
 Claim Type: Third Party
 Accident Date: 22/12/2020
 TP Veh Reg No: SLV272Z

Not Authorised
Running B4 print
85014.22

Chassis No: JTNGF3DH508000183
 Engine No:
 Reg. Date: 06/08/2015

Estimate Repair Cost to Vehicle No :SMH9315L

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	601.90	1 PC	601.90	✓
2 REAR BUMPER REFLECTOR	56.90	2 PCS	113.80	X
3 REAR BUMPER CLIP	3.50	6 PCS	21.00	—
4 REVERSE SENSOR	381.60	2 PCS	763.20	—
5 REAR TAILGATE	2,019.70	1 PC	2,019.70	—
6 TAILGATE EMBLEM - ALPHARD	68.20	1 PC	68.20	—
7 TAILGATE INNER LOCK	800.20	1 PC	800.20	—
8 TAILGATE INNER RUBBER	368.90	1 PC	368.90	X
9 REAR END PANEL OUTER	729.90	1 PC	729.90	X
10 REAR WINDSCREEN GLASS MOULDING	78.10	1 PC	78.10	—
11 REAR BUMPER LOWER cover	241.50	1 PC	241.50	X
			5,806.40	
		Less 25%	1,451.60	4,354.80
Special Net				
12 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
			40.00	40.00
Labour				
13 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
14 TO REMOVE AND REFIX REAR BUMPER ASSY, REFLECTORS, RR MOULDINGS, REFLECTORS, TOP SPOILDER, AUTO LOCK ASSY; CUT, WELD AND RENEW RR END PANEL OUTER, KNOCK AND REPAIR RR FLOOR BOARD AND RE-ALIGN TO SAME	800.00	1 LA	800.00	580
15 PUTTY AND RESPRAY ON TAILGATE, REAR FLOOR BOARD PANEL, REAR END PANEL, REAR BUMPER AND REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00	800
16 TO REMOVE AND REFIX SEAT, CARPET, GARNISH TO FACILITATE ON REPAIR S	200.00	1 LA	200.00	120
17 TO REMOVE AND REFIX REVERSE CAMERA AND REVERSE SENSOR AND RESET SYSTEM	100.00	1 LA	100.00	60
18 RUSTPROOFING	60.00	1 LA	60.00	30
			2,280.00	2,280.00
		Total	S\$ 6,674.80	
		Add GST @ 7%	467.24	
		Total Amount Payable	S\$ 7,142.04	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE