

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

14410 / Ae

ANDERSON TAN KHENG LENG
 113A BRANKSOME ROAD
 SINGAPORE 439629

Contact : 96660181

TP 1st Cap.

Ashes.

ESTIMATE

Repair Code : CLM16618

Date in : 22/12/2020

Vehicle Num. : SBV1882A

Model : B.M.W. 520I ABS SR HID M SPORT NAV

Chassis/Eng# : WBAXG12060D291705/A5180494N20B20B

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET <i>Repr</i>	1	2570.00	<i>+</i> 2,570.00
FRONT BONNET HINGES L/R <i>new</i>	2	105.00	<i>+</i> 210.00
FRONT BUMPER <i>Repr</i>	1	1490.00	<i>✓</i> 1,490.00
FRONT BUMPER FOGLAMP GARNISH OUTER MOULDING <i>new</i>	1	45.00	<i>+</i> 45.00
FRONT BUMPER INNER BRACKET LH <i>Repr</i>	1	105.00	<i>✓</i> 105.00
FRONT BUMPER LH FOGLAMP <i>cut</i>	1	315.00	<i>✓</i> 315.00
FRONT BUMPER LH FOGLAMP GARNISH <i>cut</i>	1	90.00	<i>✓</i> 90.00
FRONT BUMPER LH NOZZLE JET <i>cut</i>	1	205.00	<i>✓</i> 205.00
FRONT BUMPER LH NOZZLE JET COVER <i>cut</i>	1	55.00	<i>✓</i> 55.00
FRONT BUMPER LH NOZZLE JET COVER BRACKET <i>cut</i>	1	20.00	<i>✓</i> 20.00
FRONT BUMPER LH PARKING SENSOR <i>Repr 1 piece</i>	2	410.00	<i>250</i> 820.00
FRONT BUMPER LH PARKING SENSOR 'O' RING <i>new</i>	2	15.00	<i>✓</i> 30.00
FRONT BUMPER LH PARKING SENSOR HOLDER <i>new</i>	4	55.00	<i>80</i> <u>220.00</u>
FRONT BUMPER LOWER GRILLE <i>new</i>	1	90.00	<i>+</i> 90.00
FRONT BUMPER REINFORCEMENT <i>new</i>	1	790.00	<i>+</i> 790.00
FRONT BUMPER SIDE RETAINER L/R <i>LH new</i>	2	37.00	<i>37</i> 74.00
FRONT BUMPER SPONGE <i>cut</i>	1	72.00	<i>✓</i> 72.00
FRONT LH FENDER <i>Dented</i>	1	980.00	<i>✓</i> 980.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ANDERSON TAN KHENG LENG
 113A BRANKSOME ROAD
 SINGAPORE 439629

Contact : 96660181

ESTIMATE

Repair Code : CLM16618

Date in : 22/12/2020

Vehicle Num. : SBV1882A

Model : B.M.W. 520I ABS SR HID M SPORT NAV

Chassis/Eng# : WBAXG12060D291705/A5180494N20B20B

FRONT LH FENDER INNER BRACKET <i>cracked</i>	1	98.00	✓	98.00
FRONT LH FENDER INNER SHIELD (FRONT) <i>to be</i>	1	145.00	✓	145.00
FRONT LH HEADLAMP <i>cracked</i>	1	2950.00	2750	2,950.00
FRONT LH HEADLAMP CONTROL MODULE <i>NA</i>	1	925.00	+	925.00
FRONT LH HEADLAMP LED MODULE <i>NA</i>	2	580.00	+	1,160.00
FRONT LH HEADLAMP LOWER BRACKET <i>cracked</i>	1	7456 245.00	✓	245.00
FRONT LH HEADLAMP MODULE <i>NA</i>	1	955.00	+	955.00
FRONT LH HEADLAMP SIGNAL MODULE <i>NA</i>	1	6710.40 440.00	✓	440.00
FRONT LH HEADLAMP TOP SIDE BRACKET <i>cracked</i>	1	48.00	✓	48.00
Subtotal before discount				15,147.00
Percentage discount <i>(5%) 10%</i>				757.35
Sub-total 1				14,389.65
FRONT BONNET INSULATOR CLIPS - SET <i>NA</i>	1	60.00	+	60.00
FRONT BUMPER CLIPS - SET <i>NA</i>	1	60. 80.00	30	80.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>NA</i>	1	60.00	30	60.00
Subtotal before discount				200.00
Percentage discount 0%				0.00
Sub-total 2				200.00
Parts-total				14,589.65

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

ANDERSON TAN KHENG LENG
113A BRANKSOME ROAD
SINGAPORE 439629

Contact : 96660181

ESTIMATE

Repair Code : CLM16618

Date in : 22/12/2020

Vehicle Num. : SBV1882A

Model : B.M.W. 520I ABS SR HID M SPORT NAV

Chassis/Eng# : WBAXG12060D291705/A5180494N20B20B

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 80.00
100 400.00
750 900.00
500 700.00
x 80.00

1380

Labour Total

2,160.00

Parts & Labour Total

16,749.65

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
H/S 23/12/20

04 Days

total: 8150.40

H/S: 6.5K

6.5K