



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV09145/ONG TECK YEN Reg No/Reg Date SME5885A / 27/08/201 Date In/Mileage / 0 Chassis No GF7W0402229 Engine No 4J11YT1364 Make/Model MIT/OUTLANDER 2.0 2WD CVT ELEGANCE Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/12/2020/ 12:39	QUE	261 / Edwin Caina	61064
Description of Goods / Services					Qty Unit Price Disc% Amount

E PNT88000 / RENEW RR BUMPER	450	1350.00		
E PNT98000 / RESpray RR BUMPER & RHR FENDER	350	700.00		
A 54900099 CHECK WIRING ELECTRICAL SYSTEM		30.00		
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST		120.00		
E PNT88000 REMOVE & REFIT REVERSE SENSOR		60.00		
M SUNDRIES Sundries	20	30.00		
M FACE, RR BUMPER	1.00	807.00	23.00	621.39
M BRKT, R/BMPR FACE SIDE, RH	1.00	12.00	23.00	9.24
M REINFORCEMENT, RR BUMPER, RH	1.00	79.00	23.00	60.83
M EXTENSION, RR BUMPER	1.00	232.00	23.00	178.64
M CLIP, ENG ROOM COVER	8.00	2.00	23.00	12.32
M REFLECTOR, TAIL LAMP, RH	1.00	100.00	23.00	77.00

SURVEYOR NAME: Steve CLKK 25/1/21, 10.30am

SURVEYOR SIGNATURE: Wil Ail

DATE: P/P

REMARKS: Ry DL SM
3 days

LKK Auto Consultants hence notify

the presence of the following:

Confirm & accepted by: Ray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

	Nett	3,249.42
7% GST on	3249.42	227.46
Total Payable		3,476.88

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.