



Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1002/2020/NS

22-Dec-20

GEORGE

1 of 1

SLQ 7945 X

AUDI Q2 1.0 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
Labour			
1	To carry out first measurement test on car - o-liner	S/N \$ 800.00	? photo
2	To put the vehicle on car-o-liner to facilitate the repair.	S/N \$ 1,800.00	? photo
3	To remove and reinstall the front suspension wheel assy to facilitate the repair.	S/N \$ 2,400.00	? photo
4	To remove and reinstall engine assy and gearbox assy to facilitate the repair.	S/N \$ 2,800.00	? photo
5	To renew gearbox mechatronic and carry out adaptation.	S/N \$ 980.00	/
6	To carry out wheel alignment test.	S/N \$ 240.00	/
7	To align and repair front both chassic frames.	S/N \$ 800.00	/
Parts			
1	FRONT CHASSICFRAME COVER PLATE -LH	\$ 91.00	bt ✓
2	FRONT HEADLIGHTS COMPESATING PIECE	\$ 45.00	com ✓
3	MECHATRONIC	\$ 4,008.00	bt ✓
4	TRAMMISSION FLUID	\$ 120.00	nm ✓
GRAND TOTAL		\$ 14,084.00	

For Premium Automobiles Pte Ltd


Ram
31/12/2020
@ 1130


Authorised Signature

Subst to
making agreement
EXTRA - 7 days



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLO SLO 7945 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	
2	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	
3	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00	250 (RN) / CH-?
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY.	S/N \$ 800.00	X
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	2750 + 500 = 3250
6	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH UPPER A PILLARS AND BOTH FRONT DOORS.	\$ 7,700.00	3300
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 17,572.00	

Car-in

❖ PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG




AIK-Rasu

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 7945 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
1 FRONT BUMPER <i>de</i>		\$	1,854.00	
2 FRONT BUMPER FIXING PARTS <i>? X</i>		\$	343.00	
3 FRONT BUMPER GRILLE - CENTRE <i>de</i>		\$	195.00	
4 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>cm</i> 2	2	\$	334.00	
5 FRONT BUMPER END CAP - LH/RH <i>cm</i> / LH-X <i>X</i>		\$	68.00	
6 FRONT BUMPER SPOILER <i>cm</i>		\$	296.00	
7 FRONT BUMPER CLOSING ELEMENT <i>? cm</i>		\$	154.00	
8 WHEEL SPOILER - LH/RH <i>? X</i>	2	\$	68.00	
9 FRONT BUMPER ADAPTER - LH <i>X X</i>		\$	35.00	
10 FRONT BUMPER ADAPTER - RH <i>X de</i>		\$	42.00	
11 RADIATOR GRILLE <i>cm</i>		\$	1,395.00	
12 RADIATOR GRILLE STRIKER PLATE <i>? cm</i>		\$	123.00	
13 FRONT BUMPER CARRIER <i>? bt</i>		\$	679.00	
14 FRONT BUMPER TOP COVER <i>de</i>		\$	99.00	
15 FRONT BUMPER FOAM FILLER PIECE <i>? cm</i>		\$	77.00	
16 FRONT BUMPER GUIDE SECTION - LH/RH <i>? X</i> 2	2	\$	70.00	
17 AIRCON STICKER <i>cm</i>	NEC	\$	8.00	
18 CAUTION SIGN STICKER <i>cm</i>	NEC	\$	14.00	
19 HORN - LH LOW TONE <i>? X</i>		\$	283.00	
20 SIGNAL HORN - RH HIGH TONE <i>? X</i>		\$	180.00	
SUB TOTAL SPARE PARTS	:	\$	6,317.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLO 7945 X


S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 SPRING SHACKLE - LH/RH ? <i>bt</i>	2	\$	62.00
22 FRONT FENDER - LH/RH <i>24-rh-rh/LH 51</i>	2	\$	2,268.00
23 FRONT FENDER ATTACHMENT PARTS <i>LH-ne</i>		\$	40.00
24 FRONT FENDER BRACKET - LH/RH OUTER ?	21	\$	32.00
X 25 FRONT FENDER BRACKET - LH/RH MIDDLE ? <i>74</i>	21	\$	94.00
26 FRONT FENDER BRACKET - LH/RH INNER ?	21	\$	32.00
27 FRONT FENDER BRACE - LH/RH ? <i>bt-6</i>	21	\$	74.00
28 FRONT FENDER CLOSING ELEMENT - LH/RH ? <i>X</i>	21	\$	66.00
29 FRONT FENDER INSULATION - LH/RH ? <i>X</i>	21	\$	152.00
30 FRONT FENDER BRACKET - INNER UPPER/LOWER <i>X</i>	2	\$	46.00
31 WHEEL HOUSING LINER - LH/RH <i>X</i>	2	\$	388.00
32 WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i>		\$	57.00
33 BONNET <i>bt</i>		\$	2,757.00
34 BONNET ATTACHMENT PARTS <i>Re</i>		\$	163.00
35 BONNET LID HINGE - LH/RH ? <i>bt</i>	2	\$	122.00
36 BONNET GAS FILLED STRUT <i>X</i>		\$	101.00
37 BONNET STRIKER - LH/RH <i>bt</i>	2	\$	218.00
38 BONNET SOUND ABSORBER <i>X</i>		\$	217.00
39 BONNET IMPACT PROTECTION - CENTRE <i>rec</i>		\$	30.00
40 BONNET IMPACT PROTECTION - LH <i>rec</i>		\$	30.00
SUB TOTAL SPARE PARTS		\$	6,949.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLQ 7945 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 BONNET IMPACT PROTECTION - RH <i>1pc</i>		\$	30.00	
42 TOP FENDER LEDGE COVER - LH/RH UPPER <i>X</i>	2	\$	82.00	
43 TOP FENDER LEDGE COVER - LH/RH LOWER <i>X</i>	<i>2</i>	\$	32.00	
44 PLENUM CHAMBER COVER <i>X</i>		\$	156.00	
45 BONNET LID LOCK <i>1pc</i>	2	\$	423.00	
46 BONNET BOWDEN CAVLE - CENTRE <i>? at</i>		\$	57.00	
47 BONNET LID LOCK CABLE <i>? X</i>		\$	73.00	
48 BONNET RELEASE ELEMENT <i>? cut</i>		\$	57.00	
49 BONNET BOWDEN CABLE - LH/RH <i>? X</i>	2	\$	114.00	
50 BONNET RELEASE LEVER <i>X</i>		\$	13.00	
51 HEADLIGHT MOUNTING - LH/RH <i>? cra</i>	2	\$	234.00	
52 LED HEADLIGHT - LH/RH <i>? cra / LH-2m</i>	2	\$	9,718.00	
53 LIFT CYLINDER - LH/RH <i>? cra</i>	2	\$	282.00	
54 LIFT CYLINDER HOSE <i>? cut</i>		\$	175.00	
55 HEADLIGHT WASHER PUMP <i>X</i>		\$	151.00	
56 WINDSCREEN WASHER SYSTEM PUMP <i>X</i>		\$	121.00	
57 WASH WATER RESERVOIR <i>? de</i>		\$	173.00	
58 FRONT WHEEL COVER - LH/RH <i>? ms / LH-ne</i>	2	\$	636.00	
59 LOCK CARRIER <i>cm</i>		\$	983.00	
60 AIRCON CONDENSER <i>? 1pc</i>		\$	545.00	
TOTAL SPARE PARTS	:	\$	20,372.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLO 7945 X

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
61 REFRIGERANT LINE ? X		\$ 619.00	
62 REFRIGERANT LINE ? ?		\$ 476.00	
63 EXTERNAL TEMPERATURE SENSOR ? X		\$ 56.00	
64 ADDITIONAL RADIATOR ? bt		\$ 859.00	
65 RADIATOR ? bt		\$ 941.00	
66 RADIATOR BRACKET - UPPER ? con	2	\$ 79.00	
67 RADIATOR BUSH - LOWER ? ms	2	\$ 19.00	
68 READY MIX COOLANT ? ne		\$ 177.00	
69 RADIATOR SEALING STRIP - LH/RH ? X	2	\$ 36.00	
70 RADIATOR FAN ? sca		\$ 1,191.00	
71 RADIATOR AIR GUIDE (LH/RH) ? con	2	\$ 60.00	
72 RADIATOR AIR GUIDE - UPPER CENTRE ? con		\$ 22.00	
73 WINDOW APERTURE SEAL - LH/RH OUTER ? X	2	\$ 268.00	
74 AIR INTAKE AIR GUIDE ? con		\$ 54.00	
75 AIR INTAKE COVER ? X		\$ 28.00	
76 AIR INTAKE AIR GUIDE - OUTER ? con		\$ 64.00	
77 AIR INTAKE AIR GUIDE - INNER ??		\$ 19.00	
78 AIR INTAKE WATER DRAINAGE HOSE ? X		\$ 32.00	
79 AIR INTAKE AIR FILTER ? X		\$ 267.00	
80 AIR INTAKE MANIFOLD ? X		\$ 134.00	
81 FRONT NO PLATE st-c	S/N	\$ 60.00	
82 SUNDRIES ? X		\$ 300.00	
TOTAL SPARE PARTS	:	\$ 39,399.00	
TOTAL LABOUR CHARGES	:	\$ 17,572.00	
GRAND TOTAL	:	\$ 56,971.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.