Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Goh, Jeremy-CX Date: 24 Dec 2020

Preliminary Advice

Vehicle No : SLQ7945X Accident Date : 22/12/2020 Policy No. : 1900235871 Make : AUDI Q2 Assignment Date : 24/12/2020 **Excess** : S\$0.00 Date of Inspection : 23/12/2020 Est. Duration of Repair : 12

Inspection At : 24 BENOI SECTOR

REPAIRER: PREMIUM AUTOMOBILES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 50,654.00 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 22,114.00 |
| Check Items (Estimated) | :S\$ | 16,871.00 |
| Total | :S\$ | 38,985.00 |

Lump Sum Repair :S\$

Total Loss Consideration

Margin for Repair

| New for Old Value | :S\$ | |
|--------------------|------|------------|
| Pre-Accident Value | :S\$ | 104,000.00 |
| COE / PARF Rebate | :S\$ | 47,447.00 |
| Salvage Value | :S\$ | |

Remarks

| (X | () | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|-----|-----|---|
| (|) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
| (|) | Other comments : |

:S\$

56,553.00