



FINAL REPORT

Estimate No. : **b1 56996**
Date Estimated : **22/12/2020**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Seah Puay Lee Evelyn
87 Hillview Avenue
#05-09

Singapore 669623

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE8111D	WBA4H320X0BP26	31/05/2018	420i GC	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper panel	850	0.00	850.00	
To respray rear bumper	934	0.00	934.00	
To check electrical wiring system and lighting at the rear section.	150	0.00	150.00	
Sundries	80	0.00	80.00	
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
COVER cra (suppl)	1.00			63.45
TRIM STRIP (SPORT LINE)	1.00			99.15
REAR BUMPER PANEL PRIMED (LINE/PDC)	1.00			1,281.30

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,443.90
Total Labour & Parts :	3,457.90
Deduction for Excess :	
Total Repair Costs less Excess:	3,457.90
GST @7%:	242.05
Grand Total :	3,699.95

LOSS OF USE=\$100 X 3DAYS