

XINYA AUO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719
E-mail : xinyauto@singnet.com.sg
Tel: 6270 3481 Fax: 6278 7522

Date : 24/12/2020

Address : A M K KHORSHED ALAM
BLK 409 JURONG WEST ST.42
#010-915
SINGAPORE 640409

Reference Acknowledged: TP1250/08/20
Vehicle No Signature: SJX7105R
Make/Model Date: : MERCEDES BENZ
Insurance Co. : NTUC

- To resurvey and repair damaged parts
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

RE : QUOTATION REPAIRS TO SJX 7105R FOR THIRD PARTY CLAIMS.

PARTS REQUIRED		QTY	AMT \$
1)	FRONT BUMPER <i>de-</i>	1	\$ 1,585.00
2)	FRONT BUMPER RETAINER RH ?	1	\$ 115.00
3)	FRONT BUMPER LOWER RH CHROME <i>on</i>	1	\$ 98.00
4)	FRONT GRILLE CHROME <i>8m</i>	1	\$ 1,276.00
5)	TOW HOOK COVER <i>SCA</i>	1	\$ 95.00
6)	HEADLAMP RH <i>can</i>	1	\$ 1,196.00
7)	BUMPER CLIPS <i>re</i>	10	\$ 85.00
8)	Fender <i>bt</i>	1	\$ 4
LIST PRICE TOTAL			\$ 4,450.00
LESS DISCOUNT 10%			\$ 445.00
LIST PRICE TOTAL AFTER LESS			\$ 4,005.00
9)	<i>Not plate & casing bt</i>		\$ 50.00
NETT PRICE TOTAL			\$ 4,005.00

TOTAL PARTS COST

\$4,005.00

LABOUR AND MISCELLANEOUS CHARGES

1)	TO REMOVE & REPLACE FRONT BUMPER, GRILLE, AND TO PANEL BEAT & ALIGN.	\$ 800.00 <i>400</i> (4 days)
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER AND OTHER AFFECTED AREA. <i>& fender</i>	\$ 400.00 <i>600 400</i> (3 PANEL) <i>600</i>
3)	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP.	\$ 80.00 <i>30</i>
4)	TUFF KOTE	\$ 230.00 <i>40</i>
LABOUR TOTAL		\$ 1,510.00
TOTAL ESTIMATED REPAIR COST		\$ 5,515.00

Panel
Hp 900/10/18
5 days
4/5
29/12/2020 @ 1030

Resurvey after repair