

ASS. REC. BY:

REF:

CC4/PC120014453/R1ea3

9037

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMH 803J

at Workshop m/s PERFORMANCE

of 303, ALEXANDRA RD

Insured: FCI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 94K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMH 803J Yr Regn: 2018 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B-M.W 216 ACTIVE POWER e.c 1449

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 42416 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA2X92080VD11460

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / 3 Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R: 215/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or .

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/12/2020

Survey held at

Des. of Damages: FRT / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 18/12/2021

PERFORMANCE

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Repair Limit = 46K

Date/Time, File Pass to?



1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.S.A. (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

Mon 18/01 @ 10am
S2R

SMG803J

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

23 DEC 2020

ESTIMATE

Estimate No. : b1 56965
Date Estimated : 21/12/2020
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Chou Siaw Liang
7 One-North Gateway
#03-24

Singapore 138642

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG803J	WBA2X92080VD11460	21/11/2018	216i AT	0

DESCRIPTION	3400	VALUE
To replace rear bumper, boot lid including to knock out tail panel and to make good front bumper	2440 2550	4,250.00
To respray front bumper, rear bumper, boot lid and tail panel	3334 2665	3,704.00
To carry out body cavity preservation. (Per panel).	100	118.00
To remove and install rear windscreen glass to transfer from old to new boot lid		676.00
To conduct water leak tests.		75.00
To remove and install boot compartment carpet and garnish to facilitate repair.	231	271.00
To transfer lock mechanism from old to new bootlid including conduct check on new bootlid central locking system for proper function.	451	531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	150	177.00
To check electrical wiring system at the front and rear sections for proper function including adjustment of headlights.	250	295.00
Sundries		150.00
CUSTOMER COMMENT: After the accident, brake lights warning sign 'ON'.	na x	0.00
To check and rectify brake lights warning sign 'ON'	na x	177.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 56965
Date Estimated : 21/12/2020
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG803J	WBA2X92080VD11460	21/11/2018	216i AT	0

Total Labour 1: 10,424.00

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID <i>lt</i>	1	1,210.35	<i>1210.40</i> 1,210.35
# RR BUMPER LH SIDE GUIDE <i>7 cm</i>	1	61.35	<i>61.65</i> 61.35
RR BUMPER RH SIDE GUIDE <i>7.5 cm</i>	1	61.35	61.35
REAR BUMPER CARRIER <i>bt</i>	1	460.40	460.40
SUPPORT <i>7.5 cm</i>	1	45.55	<i>45.75</i> 45.55
RR BUMPER LH INNER SIDE GUIDE <i>7 cm</i>	1	61.35	<i>61.65</i> 61.35
RR BUMPER RH INNER SIDE GUIDE <i>7 cm</i>	1	61.35	<i>61.65</i> 61.35
# REAR BUMPER TRIM STRIP (BLAC <i>cm</i>	1	88.20	88.20
REAR BUMPER PANEL PRIMED (LINES PDC <i>de</i>	1	1,045.45	<i>1050.65</i> 1,045.45
GROMMET <i>mm</i>	4	0.80	<i>1.60</i> 3.20
PLAQUE 74MM <i>mm</i>	1	71.60	<i>71.95</i> 71.60
# REAR FLAP TOWING EYE PRIMED <i>Xmm</i>	1	43.05	43.05
PLAQUE 82MM <i>mm</i>	1	71.60	71.60
(DG) CLEANER R1 (100ML) <i>mm</i>	1	26.15	26.15
# (DG/SL) W/SCREEN SEALANT (CO <i>mm</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML <i>mm</i>	1	27.85	27.85

Total Parts : 3,601.90

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Date & Time *18/01/2021 @ 12:00* Excess S\$ _____
Surveyor's Name *Razau* Sign _____
Surveyor's Tel *90010068* Authorised Yes / No _____
Authorised Date _____ Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
Surveyor's E-mail _____
No. of Working Days Recommend *6 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	10,424.00
Parts	:	3,601.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	981.81
Grand Total	:	15,007.71

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 56965**
Date Estimated : **21/12/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Chou Siaw Liang
7 One-North Gateway
#03-24

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 138642

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMG803J	WBA2X92080VD114	21/11/2018	216i AT	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 <i>ne</i>	2.70	3.00	0.00	8.10
# SILENCER CLAMPING BUSH <i>ne</i>	54.60	1.00	0.00	54.60
# GASKET RING <i>ne</i>	30.60	1.00	0.00	30.60
# V BAND CLAMP <i>ne</i>	43.25	1.00	0.00	43.25
# HOLDER EXHAUST SYSTEM <i>ne</i>	28.75	1.00	0.00	28.75
# FRONT SILENCER <i>bt</i>	1,025.85	1.00	0.00	1,025.85
# REAR SILENCER <i>bt</i>	1,015.05	1.00	0.00	1,015.05
# MUFFLER CLAMP D=65.2MM <i>ne</i>	42.00	1.00	0.00	42.00
# TAILPIPE TRIM BRIGHT CHROME <i>sc</i>	119.55	1.00	0.00	119.55
# EXCH CATALYTIC CONVERTOR CLOSE TO E <i>bt</i>	2,118.50	1.00	0.00	2,118.50
# STEERING BOX HEAT RESISTANT PLATE <i>bt</i>	65.65	1.00	0.00	65.65
# IMPACT ABSORBER TOP <i>cm</i>	49.50	1.00	0.00	49.50
# RR BUMPER LH SIDE GUIDE <i>cm</i>	61.65	1.00	0.00	61.65
# REAR BUMPER TRIM STRIP (BLACK) <i>cm</i>	88.20	1.00	0.00	88.20
# FRT LH GRILLE (SPORT) <i>sc</i>	113.15	1.00	0.00	113.15
# FRT RH GRILLE (SPORT) <i>sc</i>	113.15	1.00	0.00	113.15
# HOOK AND LOOP FASTENER <i>ne</i>	2.85	4.00	0.00	11.40
# REAR BUMPER HEAT INSULATOR <i>bt</i>	60.90	1.00	0.00	60.90
# AIR DUCT <i>aut</i>	271.95	1.00	0.00	271.95
# EXPANDING RIVET BLACK <i>ne</i>	1.40	10.00	0.00	14.00
# CONTROL UNIT SMART OPENER <i>cm</i>	497.05	1.00	0.00	497.05
# REAR VENTILATION LH <i>cm</i>	29.55	1.00	0.00	29.55
# DECOUPING RING PDC TORQUE CONVERTER <i>ne</i>	5.15	3.00	0.00	15.45
# ULTRASONIC SENSOR IMPERIALBLAU(WA89 <i>ne</i>	371.20	2.00	0.00	742.40
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>ne</i>	131.55	2.00	0.00	263.10
#				

SUPPLEMENTARY ITEMS

Total Labour :

Total Parts : 6,883.35