

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TK MOTOR WORKSHOP

KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL: 9627 3323 FAX: 6844 2641

CO. REG NO: 53049097L

INDRIE MARLIANA TIAHJADI

Date: 30/12/2020

BLK 259 ANG MO KIO AVENUE 2 #07-08

SINGAPORE 560259

TP China.

Denise

Accident Date: 14/12/2020

Estimate Cost of Repair Bill To Mazda 6 Car NO: SLD9123G

Chassis No: JM6GL1073L0400852

1 PC FRONT BUMPER *torn*

1 PC FRONT BUMPER L/H SIDE RETAINER *Not New*

2 PC FRONT BUMPER CLIP *New*

1 PC FRONT L/H HEADLAMP *cut*

1 PC FRONT CHROME GRILLE *cut*

2 PC FRONT CHROME GRILLE CLIP *New*

✓ 1026
✓ ~~\$1,219.60~~

X \$37.80

✓ \$57.60

✓ \$3,203.80

205 ~~\$478.40~~

✓ \$22.80

30 ~~\$50.00~~

400 ~~\$450.00~~

To CHECK WIRING

To SPRAY PAINTING

To MEASURE, DRILL THE REPLACED FRONT BUMPER, POSITION
and REINSTALL FRONT PARKING SENSOR, CONTROL UNIT, CHECK & TEST
FOR FUNCTIONING

50
~~\$80.00~~

LABOUR CHARGE FOR PANEL BEATING, REMOVING ALL DAMAGE PARTS
REPLACING OF THE NEW PARTS ETC

300
~~\$380.00~~

Est: 4515.20

Less 20% 354.16

Labour: 280

total: 4392.16

TOTAL:

h/s: 35K

04 Days

\$5,980.00