

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## TK MOTOR WORKSHOP

KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL: 9627 3323 FAX: 6844 2641

CO. REG NO: 53049097L

INDRIE MARLIANA TIAHJADI

Date: 30/12/2020

BLK 259 ANG MO KIO AVENUE 2 #07-08

SINGAPORE 560259

TP Chiu.

Denise

Accident Date: 14/12/2020

Estimate Cost of Repair Bill To Mazda 6 Car NO: SLD9123G

Chassis No: JM6GL1073L0400852

1 PC FRONT BUMPER	tom	✓	1026	5. \$1,219.60
1 PC FRONT BUMPER L/H SIDE RETAINER	Not New	✗		\$37.80
2 PC FRONT BUMPER CLIP	New	✓		\$57.60
1 PC FRONT L/H HEADLAMP	cut	✓		\$3,203.80
1 PC FRONT CHROME GRILLE	cut	205		\$478.40
1 PC FRONT CHROME GRILLE CLIP	New	✓		\$22.80
0 CHECK WIRING		30		\$50.00
0 SPRAY PAINTING		400		\$450.00
0 MEASURE, DRILL THE REPLACED FRONT BUMPER, POSITION REINSTALL FRONT PARKING SENSOR, CONTROL UNIT, CHECK & TEST OR FUNCTIONING		50		\$80.00
0 LABOUR CHARGE FOR PANEL BEATING, REMOVING ALL DAMAGE PARTS REPLACING OF THE NEW PARTS ETC		300		\$380.00

List: 4515.20

Less 20% 3612.16

Labour: 780

Total: 4392.16

TOTAL:

h/s: 3.5K

04 Days

\$5,980.00