

Man: Asher

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

M/S : FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01

City House

Singapore 068877

ATTN : Motor Claim Department

Your Ref No: : SMM 8174 G

Claim Type : THIRD PARTY

Accident Date : 23/12/2020

Estimate No : M001732

Date : 28/12/2020

Veh Reg No : SMM 8174 G

Make / Model : TOYOTA SIENTA

Chassis No. : NHP1707124106

Reg. Date : 15/07/2019

not Additional
Man
24/12/20
2/5 @ 6800
Telephone After 7 days.

Estimate Repair Cost for Vehicle No. : SMM 8174 G

S/N	Description	Quantity	Unit	Price	Amount
	<u>LIST PRICE</u>			<u>SS</u>	<u>SS</u>
1	Rear Boot <i>Body</i>	1	PCS	1,250.40	1,250.40 ✓
2	Rear Boot Lock <i>JM</i> <i>409.20</i>	1	PCS	509.10	509.10 ✓
3	Rear Boot Lock Catch <i>ny</i>	1	PCS	40.20	40.20 X
4	Rear Boot Rubber <i>twi</i> <i>281.10</i>	1	PCS	349.40	349.40 ✓
5	Rear Boot Emblem <i>nel</i>	1	PCS	49.10	49.10 ✓
6	Rear Boot Centre Logo <i>nel</i> <i>68.10</i>	1	PCS	95.30	95.30 ✓
7	Rear Boot Top Hinge <i>nn</i>	2	PCS	48.60	97.20 X
8	Rear Boot Shock Absorber <i>nn</i>	2	PCS	299.40	598.80 X
9	Rear Boot Centre Garnish <i>Body/cra</i>	1	PCS	247.90	247.90 ✓
10	Rear Boot Inner Cover <i>de/to.1</i> <i>366.10</i>	1	PCS	606.40	606.40 ✓
11	Rear Boot Inner Cover Clip <i>nel</i> <i>45.00</i> <i>14/304</i>	1	PCS	550	77.00 ✓
12	Rear Boot Inner Pull Handle Garnish <i>dis</i>	1	PCS	58.60	58.60 ✓
13	Rear Compartment Panel <i>cramped/suc</i>	1	PCS	786.40	786.40 ✓
14	Rear Compartment Panel Top Cover (RH) <i>ny</i>	1	PCS	298.20	298.20 X
15	Rear Compartment Panel Top Cover (LH) <i>ny</i>	1	PCS	267.40	267.40 X
16	Rear Compartment Panel Top Cover Clip (LH) <i>nn</i>	4	PCS	5.50	22.00 X
17	Rear Tool Tray <i>twi</i>	1	PCS	394.10	394.10 ✓
18	Rear Fender Inner Side-trims <i>de</i> <i>de/to.1</i> <i>2 481</i>	2	PCS	652.40	962.00 <i>1,304.80</i> ✓
19	Rear End Panel <i>outer</i> <i>Body</i>	1	PCS	517.40	366.10 <i>517.40</i> ✓
20	Rear End Panel Top Garnish <i>dis</i> <i>266.10</i>	1	PCS	299.40	299.40 ✓
21	Rear Smart sensor <i>cra</i>	1	PCS	296.20	296.20 ✓
22	Rear Bumper <i>dis</i>	1	PCS	606.40	606.40 ✓
23	Rear Bumper Centre Protector <i>dis</i>	1	PCS	212.40	212.40 ✓
24	Rear Bumper Side Protector (LH) <i>cra</i>	1	PCS	166.90	166.90 ✓
25	Rear Bumper Reflector (LH) <i>cra</i>	1	PCS	66.40	66.40 ✓
26	Rear Bumper Towing Cover <i>cra</i>	1	PCS	38.20	38.20 ✓
27	Rear Bumper Lower Clips <i>nel</i>	7	PCS	5.50	38.50 ✓
28	Rear Buper Side Retainer <i>na</i>	2	PCS	80.00	160.00 X
29	Rear Taillamp (LH) <i>nn</i>	1	PCS	467.20	467.20 X
30	Rear End Panel <i>inner</i> <i>Body</i>	1	PCS	695.40	695.40 ✓

TOTAL :	10,616.70
DISCOUNT 25% :	2,654.18
SUB TOTAL :	7,962.52

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

M/S : FIRST CAPITAL INSURANCE LIMITED

36 Robinson Road

#16-01

City House

Singapore 068877

ATTN : Motor Claim Department

Your Ref No: : SMM 8174 G

Claim Type : THIRD PARTY

Accident Date : 23/12/2020

Estimate No : M001732

Date : 28/12/2020

Veh Reg No : SMM 8174 G

Make / Model : TOYOTA SIENTA

Chassis No. : NHP1707124106

Reg. Date : 15/07/2019

Estimate Repair Cost for Vehicle No. : SMM 8174 G**SPECIAL NET**

1	Rear Bumper Sensor	1	Set PCS	SS 300.00	short 200	SS 300.00
2	Rear Windscreen Gum sealant	1	SET	SS 80.00	neu 40	SS 80.00
3	Rear Number Plate	1	PCS	SS 50.00	nr X	SS 50.00
TOTAL :						430.00
DISCOUNT 10% :						43.00
SUB TOTAL :						387.00

LABOUR CHARGES

1	Panel Beating			SS 1250	SS 1,800.00
2	Check Wiring and Diagnosis Test			30	240.00
3	Rust Proofing			80	80.00
4	To Remove & Refix Rear Windscreen			120	160.00
5	To remove & Refix Rear Bumper Sensor			50	80.00
6	To remove, Refix Rear Seat and holster			80	160.00
7	To Spray Painting			900	1,000.00
TOTAL					3,520.00
GRAND TOTAL					11,869.52

FOR FOCUS AUTO PTE LTD**Jenny Koh****Claims Executive****HP: 8139 9800**

AUTHORISE SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-7670.60
251
P-5752.95
S-N-240.00
L-2510.00
8002.95
6802