

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS20014458/UVD3E2

Date: 11/01/2021

REFERENCE

Insured/Claimant: MOHAMED MUZIFER HUSSAIN S/O FAIZAL
MOHAMED

Policy No: MPC20A00045600

Date of Loss: 21/12/2020

Nature of Claim: OD Claim No: DMPC2000249H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ1701J**
Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CXS075904
Reg. Date: 16/06/2014 (Man. Year: 2014) Chassis No: WAUZZZ8V4E1027203
Colour: Black Odometer: 72956 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$44,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Goodyear 7 mm Rear Left Side: Goodyear 7 mm
Front Right Side: Goodyear 7 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,117.50	1,518.00	599.50	28.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	1,020.00	410.00	28.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,547.50	2,538.00	1,009.50	28.46
- Excess (\$\$)	0.00	600.00	-600.00	
(\$\$)	3,547.50	1,938.00	1,609.50	45.37
+ GST 7.00/7.00% (\$\$)	248.33	135.66	112.67	45.37
Nett Amount (\$\$)	3,795.83	2,073.66	1,722.17	45.37

INSPECTION

Date of Assignment: 24/12/2020 Present Location: SME Motor Pte Ltd (Kaki Bukit)
SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 24/12/2020 Inspected At: 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Please be informed that insured have withdrawn the OD claim.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$132.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jan 2021)
Parts:	144	AUDI A3 1.4 SEDAN TFSI (AMBIENTE) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ1701J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Distorted	800.00 F	*800.00 F
2	1		*REAR BUMPER RETAINER RH (WCP)	Bent	50.00 F	*50.00 F
3	10		*REAR BUMPER CLIP (WCP)	Necessary	40.00 F	*40.00 F
4	1		*REAR BUMPER REFLECTOR RH (WCP)	Cracked	40.00 F	*40.00 F
5	1		*REAR RH TAIL LAMP (WCP)	Cracked	450.00 F	*450.00 F
6	1		*REAR RH TAIL LAMP PANEL (WCP)	Repair	160.00 F	*- F
7	1		*REVERSE SENSOR RH (WCP)	Repair	120.00 F	*- F
8	1		*REAR BUMPER REINFORCEMENT (WCP)	Not Necessary	265.00 F	*- F

F=Franchise part.

Sub Total (S\$)	1,925.00	1,380.00
+ Margin on L,N Items 10.00/10.00% (S\$)	192.50	138.00
Total Parts (S\$)	2,117.50	1,518.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WIRE CHECKING	New	30.00	20.00
2	LABOUR CHARGE	New	700.00	520.00
3	SPRAY PAINTING	New	700.00	480.00
Gross Labour Cost (\$\$)			1,430.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >