



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI20014466/Qvd3e2	
			Date: 08/02/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9725H	Veh. Inspected	SKX 2269Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D20005276MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	24/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 6 2.0L	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6GJ1072G0221064	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2020	Inspection Date	28/12/2020	
Survey held at	BLK 1 SIN MING IND EST SEC C#01-129			
Repairer	KENG HOCK AUTO			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	