

KENG HOCK AUTO

Sik. 1, Sin Ming Industrial Estate C, #01-129, Singapore 575636

Fax : 6458 - 5589 / H/P : 9657 - 1534

Date : 28/12/20

Quotation: SKX 2269Y

1	Front headlamp assy / SCR	\$3209.30
2	Front fender / DD	\$398.40
3	Front fender top rubber seal X500	\$99.70X
4	Front fender inner shield clips / 100	\$40.00
5	Front fender inner shield / cut.	\$195.60
6	Bumper / CRU.	\$1280.00 / 151.30
7	Bumper side retainer / BR	\$39.80
8	Sport rim / SCR	\$700.00

Less 20%

5,734.40
- 20%
4,587.52

To focus headlamp & Computerised
resetting

\$150.00 50

To wheel alignment

\$150.00 60

panel beating

\$800.00 450

Spray-painting

\$800.00 400

960

Repair day 4 days.

LIS

After paint photo.

Sun Pin (LKK)

28/12/2020

TP without prejudice

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4,587.52

960

5,547.52

- 20%

4,438.02

LIS

\$4,450

4 days

