

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 04 Jan 2021

## **Preliminary Advice**

Insured Vehicle No : YJ9823J  
TP Vehicle No : GBF4214T  
Make : HINO XZU710R-HKFMS3  
Date of Inspection : 24/12/2020  
Inspection At : LIU'S BROTHER AUTO WORKSHOP (HQ)  
1 KAKI BUKIT AVE 6 #01-01, AUTO BAY@KAKI BUKIT  
SINGAPORE 417883  
Accident Date : 17/12/2020  
Assignment Date : 24/12/2020  
Est. Duration of Repair : 3

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,559.30
Revised Amount	:S\$	3,626.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,626.24
Lump Sum Repair	:S\$	2,900.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :