

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SMT8461R
 Chassis No : JHMGK3850LS218008
 Model : JAZZ 1.3LXR CVT 20YM (EURO 6)
 Owner's Name : LAB SCIENCE SOLUTION PTE LTD
 Ins Policy No. :
 Date of Accident : 18/12/2020

Document No. : SQT20004176 Page 2
 Date : 21. Dec 2020
 Customer No. : WZF002
 Svc Advisor : IVAN TEO BOON KIAT
 Engine No : L13B15000785
 Date | Time : 21. Dec 2020 2:35:54 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BOSUN	SUNDRIES	1	100.00	50	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	280.00	✓	280.00	19.60	299.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	280.00	✓	280.00	19.60	299.60
BKDR12R	REMOVE & TRANSFER ITEMS TO NEW FR R DR. ADJUST	1	650.00	✓	650.00	45.50	695.50
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	650.00	✓	650.00	45.50	695.50
BPBODY	RENEW FRONT RIM	1	100.00	80	100.00	7.00	107.00
BPBODY	RENEW REAR RIM	1	100.00	80	100.00	7.00	107.00
BKFE22K	STRAIGHTEN ALIGN RR R FENDER AND RENEW DAMAGE PART	1	5200.00	3250	5200.00	364.00	5564.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)	1	4680.00	3640	4680.00	327.60	5007.60
Sum Labor					12040.00	842.80	12,882.80
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

Survey By

Date & Time

Excess

Status

Signature

Total Amount 16,048.55 1,123.40 17,171.95

Total (Inclusive of GST) 17,171.95

Printed on 21/12/2020 3:21:25 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No: M200050223

Company Ref No: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMT8461R
Chassis No : JHMGK3850LS218008
Model : JAZZ 1.3LXR CVT 20YM (EURO 6)
Owner's Name : LAB SCIENCE SOLUTION PTE LTD
Ins Policy No :
Date of Accident : 18/12/2020

Document No. : SQT20004176
Date : 21. Dec 2020
Customer No. : WZF002
Svc Advisor : IVAN TEO BOON KIAT
Engine No : L13B15000785
Date | Time : 21. Dec 2020 2:35:54 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: LAB SCIENCE SOLUTION PTE LTD OWNER INSURER: Tokio Marine ACC DATE: 18/12/2020 SURVEYED BY: DATE: REF NO: TP INSURER: MSFIRST CAPITAL TP VEH: SHC3508Y						
04711-T5A-J50ZZ	FACE,FR.BUMPER	1	517.70	25	388.27	27.18	415.45
71193-T5A-000	SPACERR.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	19	2.30	25	32.77	2.29	35.06
60211-T5R-A00ZZ	PANEL ,R.FR.FENDER	1	408.90	25	306.67	21.47	328.14
33100-T5A-J81	HEADLIGHT ASSY,R.	1	492.10	25	369.07	25.83	394.90
67010-T5A-U00ZZ	PANEL COMPR.FR.DOOR	1	792.40	25	594.30	41.60	635.90
67324-T5A-003	TAPE SETR.FR.DOOR	1	34.50	25	25.87	1.81	27.68
67510-T5A-N10ZZ	PANEL COMP,R.RR.DOOR	1	736.20	25	552.15	38.65	590.80
67825-T5A-003	TAPER.RR.DOOR SASH	1	15.40	25	11.55	0.81	12.36
04636-T5A-300ZZ	PANEL SETR.RR.OUTSIDE	1	585.30	25	438.97	30.73	469.70
04715-T5A-J50ZZ	FACE,RR.BUMPER	1	492.70	25	369.52	25.87	395.39
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
42700-T5S-M72	WHEEL,DISK AL 15X7	1	457.20	25	342.90	24.00	366.90
42700-T5S-M72	WHEEL,DISK AL 15X7	1	457.20	25	342.90	24.00	366.90
Sum Item					3828.55	268.00	4,096.55

Printed on 21/12/2020 3:21:25 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.