

Our Job Ref No 305440636
Date : 11.01.21

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : Mr TAUFIKH
Vehicle Reg No. SH6989R CTPL 22.12.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBQ6777P
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,350.00
Final Lumpsum Repair cost \$1,350.00

3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156

Signature : 
Name : Taufikh
Date : 15/1/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305440636
 REGN NO : SH 6989R
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 12.11.2015
 DATE/TIME IN : 23.12.2020 12:50
 ACCIDENT DATE : 22.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	1,106.00	20.00	884.80	del	
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	del	
0003	04-01-0103-1150-A	I40VC PROTECTOR MAT	1 N	50.00	2.00-	50.00	del	
0004	04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	228.00	20.00	182.40	X nn	
SUB-TOTAL : 1,134.80								1,128 -20% 902.40 +Nett 50 952.40

JOB NATURE

0000	20-05	REAR BUMPER ADVERTISMENT LOGO				50.00	del	760
0001	L	PANEL BEATING (repair rr fender Lh)		420.00		280		1,712.40
0002	23-502	SPRAYPAINT ON AFFECTED AREA		450.00		400		-20%
0003	20-22	REMOVE/REFIX REVERSE SENSOR		80.00		30		1,369.92
SUB-TOTAL : 1,000.00								1,350 2 days

Tanpin 97495740
 WP 23/12/20 5pm

02 days
 US Resing after repair \$1,350/-
 for part & labour in