

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2377U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|-------------------------|------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | DEFORMED | 1,106.00 | 1,106.00 |
| 1 | REAR BUMPER LOWER COVER | NOT NECESSARY | 228.00 | - |
| 1 | REAR BUMPER BRACKET LH | DEFORMED | 35.00 | 35.00 |
| 1 | LH ROCKER GARNISH | TO REPAIR SEE LABOUR | 732.80 | - |
| 1 | REAR LH DOOR PANEL | TO REPAIR SEE LABOUR | 2,201.10 | - |
| 1 | REAR LH FENDER | BENT | 2,171.40 | 2,171.40 |
| 1 | REAR SHOCK ABSORBER LH | NOT NECESSARY | 341.85 | - |
| 1 | REAR UPPER ARM LH | NOT NECESSARY | 335.75 | - |
| 1 | REAR LOWER ARM LH | NOT NECESSARY | 353.80 | - |
| 1 | REAR WHEEL BEARING W/HUB | NOT NECESSARY | 724.00 | - |
| 1 | FUEL TANK OUTER GARNISH | DEFORMED | 59.40 | 59.40 |
| 1 | REAR WHEEL CAP LH | DEFORMED | 214.20 | 214.20 |
| | LESS 20% DISCOUNT | | -1,700.66 | -717.20 |
| | | | 6,802.64 | 2,868.80 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR BUMPER MAT (SN) | NECESSARY | 50.00 | 50.00 |
| 1 | REAR BUMPER REVERSE SENSOR (SN) | NOT NECESSARY | 135.70 | - |
| 1 | REAR DOOR COMFORT APP STICKER (SN) | NECESSARY | 80.00 | 80.00 |
| 1 | REAR TYRE (SN) | NOT NECESSARY | 216.00 | - |
| | | | 481.70 | 130.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING .INCLUSIVE OF THE REPAIR OF LH ROCKER GARNISH AND REAR LH DOOR PANEL . | | 800.00 | 700.00 |
| | SPRAY PAINTING CHARGE . | | 800.00 | 700.00 |
| | RENIVE/REFIX DOOR PARTS. | NOT NECESSARY | 120.00 | - |
| | TUFF COAT. | | 120.00 | 30.00 |

Report Ref No. NS/INC20014477/T1qd3q2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|-----------|------------------------------|-------------------|
| | REMOVE /REFIX REAR LH UPHOLSTERY . | | 90.00 | 60.00 |
| | | | 1,930.00 | 1,490.00 |
| | GRAND TOTAL | | 9,214.34 | 4,488.80 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 3,550.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |
| (CONFIRMED) | | |
| | | |

Report Ref No. NS/INC20014477/T1qd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.