

REPAIR ESTIMATE*

VEHICLE NO SHB2377u
MAKE HYUNDAI
MODEL I-40

DATE 22.12.20
MVA CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$1,106.00
1	REAR BUMPER LOWER COVER			\$228.00
1	REAR BUMPER BRACKET LH			\$35.00
1	LH ROCKER GARNISH			\$732.80
1	REAR LH DOOR PANEL			\$2,201.10
1	REAR LH FENDER			\$2,171.40
1	REAR SHOCK ABSORBER LH			\$341.85
1	REAR UPPER ARM LH			\$335.75
1	REAR LOWER ARM LH			\$353.80
1	REAR WHHEEL BEARING W/ HUB			\$724.00
1	FUEL TANK OUTER GARNISH			\$59.40
1	REAR WHEEL CAP LH			\$214.20
	SUB TOTAL		3586	\$8,503.30
	20.00%			\$1,700.66
	DISCOUNTED TOTAL		20% - 2868.80	\$6,802.64
1	REAR BUMPER MAT			\$50.00
1	REAR BUMPER REVERSE SENSOR			\$135.70
1	REAR DOOR COMFORT APP STICKER			\$80.00
1	REAR TYRE			\$216.00
			130.	\$481.70
	Labour Charge			
	Panel Beating			\$800.00
	Spray Painting Charge			\$800.00
	Remove/refix door parts		1490	\$120.00
	Tuff coat			\$120.00
	Remove/refix rear lh upholstery			\$90.00
	TOTAL LABOUR		4488.80	\$1,930.00
	ESTIMATE TOTAL		4533.50	\$9,214.34
			# 4 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 9749549
WV 23/12/20 2pm
1/2 Resurvey after repair
04 days
Taufik @ hkmto-wv

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: