

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7535Y**AAD2012-***Not Authoised
Permy B4 paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

23 DEC 2020**TOTAL PARTS****SHB7535Y**

JTDKB3FU103077070

TOYOTA

PRIUS

22/12/2020

AIG

04/12/2018

PART		LIST	
1	COVER, REAR BUMPER	\$	442.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70 ✓
1	GUARD, REAR BUMPER, CENTER	\$	576.30 ✓
1	COVER, REAR BUMPER, LOWER	\$	15.40 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$	116.50 X
1	RETAINER, REAR BUMPER SIDE, RH	\$	117.70 ✓
1	FILLER, REAR BUMPER EXTENSION, RH	\$	123.70 ✓
1	SEAL, REAR BUMPER SIDE, RH	\$	88.50 X
1	LENS & BODY, REAR COMBINATION LAMP, RH	\$	451.80 X
1	LENS AND BODY, REAR LAMP, RH	\$	502.00 ✓
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30 X
1	COVER, FLOOR UNDER, NO.1 (LH)	\$	175.10 X
1	COVER, FLOOR UNDER, NO.2 (RH)	\$	241.90 X
1	COVER, REAR FLOOR (CTR)	\$	229.90 X
TOTAL		\$	4,064.40
25%		\$	1,016.10
		\$	3,048.30

Special Nett

1SET PARKING AID	\$	700.00 2 501n
1SET REAR BUMPER CLIP	\$	95.00 601n
1 REAR BUMPER PROTECTOR	\$	180.00 301n
1SET REAR FENDER LINER CLIP	\$	85.00 X
1SET REAR BUMPER RETAINER CLIP	\$	85.00 X
1SET TAILLAMP LOWER CLIP	\$	55.00 X
1SET TAILLAMP UPPER CLIP	\$	55.00 151n
1 END PANEL TRIM CLIP	\$	65.00 X
TOTAL	\$	1,320.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7535Y

AAD2012-

TOTAL PARTS \$ 4,368.30**LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 300

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 X

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ 480.00 X

To transfer of Fender fittings, attachments and perform water seepage test.

\$ 480.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ 380.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 X

Towing Fees

\$ 150.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 300

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7535Y

To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To lift-up / out engine with gear box and refit.	\$	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	X
TOTAL	\$	9,990.00	
Over All Total	\$	14,358.30	

(PART-BY-PART) Repair Days

25 DAYS

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: