

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7535Y**AAD2012-**

Not Authorized
Permy B4 paint
82867.80

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

23 DEC 2020**SHB7535Y**

JTDKB3FU103077070

TOYOTA

PRIUS

22/12/2020

AIG

04/12/2018

PART**LIST**

1 COVER, REAR BUMPER	\$	<i>Per</i> 442.60	✓
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	<i>By</i> 332.70	✓
1 GUARD, REAR BUMPER, CENTER	\$	<i>Per 100</i> 576.30	✓
1 COVER, REAR BUMPER, LOWER	\$	<i>mt</i> 15.40	✓
1 RETAINER, REAR BUMPER SIDE, LH	\$	<i>SL</i> 116.50	X
1 RETAINER, REAR BUMPER SIDE, RH	\$	<i>D-1</i> 117.70	✓
1 FILLER, REAR BUMPER EXTENSION, RH	\$	<i>mgmt</i> 123.70	✓
1 SEAL, REAR BUMPER SIDE, RH	\$	<i>SL</i> 88.50	X
1 LENS & BODY, REAR COMBINATION LAMP, RH	\$	<i>SL</i> 451.80	X
1 LENS AND BODY, REAR LAMP, RH	\$	<i>CR</i> 502.00	✓
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>R</i> 650.30	X
1 COVER, FLOOR UNDER, NO.1 (LH)	\$	<i>SL</i> 175.10	X
1 COVER, FLOOR UNDER, NO.2 (RH)	\$	<i>SL</i> 241.90	X
1 COVER, REAR FLOOR (CTR)	\$	<i>SL</i> 229.90	X
TOTAL	\$	4,064.40	
25%	\$	1,016.10	
	\$	3,048.30	

Special Nett

1SET PARKING AID	\$	<i>NU</i> 700.00	2500
1SET REAR BUMPER CLIP	\$	<i>NU</i> 95.00	6000
1 REAR BUMPER PROTECTOR	\$	<i>NU</i> 180.00	3000
1SET REAR FENDER LINER CLIP	\$	<i>NU</i> 85.00	X
1SET REAR BUMPER RETAINER CLIP	\$	<i>NU</i> 85.00	X
1SET TAILLAMP LOWER CLIP	\$	<i>NU</i> 55.00	X
1SET TAILLAMP UPPER CLIP	\$	<i>NU</i> 55.00	1500
1 END PANEL TRIM CLIP	\$	<i>NU</i> 65.00	X
TOTAL	\$	1,320.00	

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7535Y

TOTAL PARTS	\$	4,368.30
--------------------	-----------	-----------------

LABOUR

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	300
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Towing Fees	\$	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	500

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7535Y**AAD2012-**

To reinstall rear bumper parking sensor.	\$	170.00	501
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 220.00	X
To replace, refix and top up coolant for radiator	\$	4 170.00	X
To lift-up / out engine with gear box and refit.	\$	4 440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	4 380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	4 380.00	X
TOTAL	\$	9,990.00	
Over All Total	\$	14,358.30	

(PART-BY-PART) Repair Days**25 DAYS****2 1/2 day**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: