

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD251B**AAD2012-***Not Authorised**1 Rm @ 5000*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model: **23 DEC 2020**
 Date of Accident :
 Third Party Insurer :
 Date of Registration :

SHD251B

VF1ABL15AUC282166

RENAULT

LATITUDE

22/12/2020

AIG

03/11/2015

	PART		LIST	
1	1 BUMPER COVER REAR	\$	Bu 561.70	✓
2	1 BUMPER LOWER REAR	\$	BH/CM 411.90	✓
3	1 BUMPER BRACKET CTR REAR	\$	SL 98.10	X
4	1 BUMPER BRACKET SIDE RH REAR	\$	SL 82.10	X
5	1 BUMPER RETAINER RH REAR	\$	SL 59.80	✓
7	1 BUMPER BRACKET SIDE LH REAR	\$	DT 80.80	✓
8	1 BUMPER RETAINER LH REAR	\$	DT 54.20	✓
10	1 BUMPER BEAM REAR	\$	B 547.80	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	B 114.50	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	B 114.50	X
13	1 OUTER PANEL REAR (End Panel)	\$	B 745.80	✓
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL 404.56	X
15	1 BOOT REAR	\$	B 1,677.20	✓
16	1 BOOT FINISHER	\$	SL 344.70	X
17	1 BOOT STRUT LH	\$	SL 145.10	X
18	1 BOOT STRUT RH	\$	SL 145.10	X
19	1 BOOT HINGE LH	\$	N 254.20	✓
20	1 BOOT HINGE RH	\$	N 254.20	X
21	1 BUMPER REFLECTOR LH	\$	CM 16.60	✓
		\$	6,112.86	
		10% \$	611.29	
		\$	5,501.57	

Special Nett

1	1SET PARKING AID	\$	Short 700.00	4000
2	1SET REAR BUMPER CLIP	\$	N 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	N 33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	N 10.00	X

Trans-cab Auto Services Pte Ltd**AAD2012-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD251B

5 1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00	X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
7 1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	nn	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
10 1SET WHEELARCH CLIP	\$	nn	60.00	X
11 1SET FENDER CLIP	\$	nn	35.00	X
12 1 EXHAUST MOUNTING REAR	\$	nn	17.82	X
TOTAL	\$		1,059.82	
TOTAL PARTS	\$		6,561.39	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	8001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
TOTAL	\$	7,070.00	