

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G

AAD2012-161

Not Authorized
1/1 Emp @ 1550/h

SHD401K

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

23 DEC 2020

SHD401K

VF1ABL15AUC283412
RENAULT
LATITUDE
21/12/2020
CHINA
17/10/2016

PART			LIST	
1	1 BUMPER COVER REAR	\$	<i>Bu</i> 561.70	✓
2	1 BUMPER LOWER REAR	\$	<i>Act</i> 411.90	✓
3	1 BUMPER REFLECTOR LH	\$	<i>Pu</i> 16.60	X
4	1 BUMPER BRACKET CTR REAR	\$	<i>Lu</i> 98.10	X
5	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Pu</i> 82.10	X
6	1 BUMPER RETAINER RH REAR	\$	<i>Lu</i> 59.80	X
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Lu</i> 80.80	X
8	1 BUMPER RETAINER LH REAR	\$	<i>Lu</i> 54.20	X
##	1 BUMPER BEAM REAR	\$	<i>Bu</i> 547.80	✓
		\$	1,913.00	
		10% \$	191.30	
		\$	1,721.70	

Special Nett				
1	1SET PARKING AID	\$	<i>Pu</i> 700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>Lu</i> 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	X
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00	✓
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	X
	TOTAL	\$	839.00	
	TOTAL PARTS	\$	2,560.70	

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00

2201

Trans-cab Auto Services Pte Ltd

AAD2012-161

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD401K

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	170.00	✓
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	✓
To repair and realign rear exhaust pipe.	\$	170.00	✓
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	✓
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	✓
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	✓
To check steering geometry and computer wheel alignment	\$	220.00	✓
To Check Electrical Lighting Concerned.	\$	170.00	✓

TOTAL \$ 7,580.00**Over All Total \$ 11,862.40****(LUMP SUM)****Repair Days****10 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: