

RICO60

AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
Lump Sum	
ERV	35K

TO: AXA	LKK.
Vehicle No : SMG620U	
Make & Model : VW POLO	
DATE:27/12/2020	

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAILGATE <i>Rp</i>	1	\$ X 2,001.30	\$ 2,001.30
2	TAILGATE EMBLEM (POLO) <i>ndc</i>	1	\$ 133.30	\$ 133.30
3	TAILGATE STOPPER <i>nn X</i>	2	\$ X 20.00	\$ 40.00
4	TAILGATE LOCK ASSY <i>nn X</i>	1	\$ X 445.90	\$ 445.90
5	TAILGATE LOCK DETECTOR <i>cnr</i>	1	\$ X 258.00	\$ 258.00
6	TAILGATE LOCK DETECTOR BRACKET <i>cnr</i>	1	\$ X 48.00	\$ 48.00
7	TAILGATE STRIKER <i>nn X</i>	1	\$ 74.50	\$ 74.50
8	TAILGATE WEATHERSTRIP <i>fwi</i>	1	\$ 298.80	\$ 298.80
9	TAILGATE INNER TRIM BOARD <i>nn X</i>	1	\$ X 667.80	\$ 667.80
10	REAR WINDSCREEN MOULDING <i>nn X</i>	1	\$ X 180.70	\$ 180.70
11	TAILLAMP <i>LH-cnr RH-Xnn</i>	2	\$ X 788.90	\$ 1,577.80
12	TAILLAMP BOTTOM RETAINER <i>LH-cnr RH-Xnn</i>	2	\$ (109.00)	\$ 218.00
13	REAR BUMPER <i>de</i>	1	\$ 1,777.40	\$ 1,777.40
14	REAR BUMPER DIFFUSER <i>de</i>	1	\$ 760.00	\$ 760.00
15	REAR BUMPER SIDE RETAINER <i>LH-cnr RH-Xnn</i>	2	\$ (120.00)	\$ 240.00
16	REAR BUMPER CENTER BRACKET <i>cnr</i>	1	\$ 158.00	\$ 158.00
17	REAR BUMPER REINFORCEMENT <i>bt</i>	1	\$ 918.00	\$ 918.00
18	REAR BUMPER LOWER BRACKET <i>Xnn</i>	2	\$ 185.40	\$ 370.80
19	REAR BUMPER REVERSE SENSOR <i>nn / 2 NEC</i>	2	\$ 190 385.00	\$ 1,580.00
20	REAR REVERSE SENSOR WIREHARESS <i>nn X</i>	1	\$ 542.00	\$ 542.00
21	REAR BUMPER REVERSE SENSOR HOLDER <i>nn</i>	4	\$ 20.00	\$ 80.00
22	REAR BUMPER LICENSE PLATE LAMP <i>dis</i>	2	\$ 85.30	\$ 170.60
23	REAR END PANEL <i>bb</i>	1	\$ 1,477.30	\$ 1,477.30
24	REAR END PANEL TOP GARNISH <i>de</i>	1	\$ 245.00	\$ 245.00
25	REAR FLOOR PANEL TOP BOARD <i>de</i>	1	\$ 746.30	\$ 746.30
26	REAR FLOOR PANEL LOWER SIDE COVER RH <i>Xnn</i>	1	\$ 228.50	\$ 228.50

225

4473.10

965.57

268.65

501.08

380.

639.15

225

420.

27	REAR FENDER INNER TRIM	LH de RH X NN	2	\$	878.60	\$	1,757.20
28	REAR AIR VENT	eng ✓	1	\$	128.90	\$	128.90
29	REAR EXHAUST PIPE	NN X	1	\$	1,245.00	\$	1,245.00
30	REAR EXHAUST PIPE MOULTING	NN X	2	\$	54.00	\$	108.00
5968.45 10% - 5371.60							
Subtotal :						\$	18,477.10
Less 10%						\$	1,847.71
Parts Total :						\$	16,629.39

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR WINDSCREEN SEALANT	X	1 \$ 90.00	\$ 90.00
2	REAR WINDSCREEN INNER SEAL	X	1 \$ 80.00	\$ 80.00
3	TAILGATE SEALANT	X	1 \$ 90.00	\$ 90.00
4	TAILGATE INNER TRIM BOARD CLIP SET	X	1 \$ 70.00	\$ 70.00
5	REAR BUMPER CLIP SET	30 ng	1 \$ 70.00	\$ 70.00
6	REAR END PANEL TOP GARNISH CLIP SET	10 ng	1 \$ 45.00	\$ 45.00
7	REAR END PANEL SEALANT	40 ng	1 \$ 80.00	\$ 80.00
8	REAR FENDER INNER TRIM CLIP SET	40 ng	1 \$ 85.00	\$ 85.00
9	REAR FLOOR PANEL LOWER SIDE COVER CLIP	NN X	1 \$ 30.00	\$ 30.00
120				\$ 640.00

LABOUR		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	800	\$ 1,200.00
TO SPRAY PAINT AFFECTED AREA(SPECIAL COLOUR)	800	\$ 1,500.00
REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	30	\$ 150.00
PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	30	\$ 150.00
REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY. PERFORM AIMING AND ADJUST TO POSITION.	NN X	\$ 150.00
CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	NN X	\$ 120.00
TRANSFER TAILGATE ATTACHMENT AND MECHANISM INTO NEW TAILGATE ASSY. RE-ALIGN TO POSITION.	NN X	\$ 150.00
DISMENTLE AND RE-INSTALL REAR INTERIOR COMPARTMENT TRIMMING.	60	\$ 200.00
APPLY TUFF COATING TREATMENT.	30	\$ 200.00
REMOVE AND REFIT TAIL GATE WINDSCREEN	NN X	\$ 150.00
1750.		
LABOUR TOTAL		\$ 3,970.00

	Total Parts Cost	\$	17,269.39
	Total Labour Cost	\$	3,970.00
	Total Repair Cost	\$	21,239.39

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

Taufik 97495749

29/12/20 @ 11am

L/S Resurvey after repair

taufik@lkhauto.com.

6 days

5371.60

120

1750

7241.60

158'5800

6 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: