



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /TAN FANG LING (CHEN FANGLING) Reg No/Reg Date SMW1658X / 05/11/202 Date In/Mileage 26/12/2020/ 0 Chassis No MMBSTA13AMH001309 Engine No 3A92UJS5395 Make/Model MIT/21MY ATTRAGE 1.2 CVT (E31) Colour/Trim A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	26/12/2020/ 10:36	QUK	282 / Kevin Leong	61168		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT RH FENDER & AFFECTED AREA 450 X2						675	1350.00
E PNT98000 PAINT WORK ON FRT BUMPER & FRT RH FENDER 350 X2							700.00
M SUNDRY PERFORM RUST PREVENTION							40.00
M SUNDRY TO TRANSFER FRT RH RIM INCLUDING BALANCING							30.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUNDRIES						20	50.00
M HEADLAMP ASSY, RH BR 1 X N/A				1.00	1697.00	23.00	1306.69
M TANK, WINDSHIELD WASHER MIS				1.00	74.00	23.00	56.98
M CAP, WASHER TANK FILLER				1.00	7.00	23.00	5.39
M FACE, FR BUMPER BR 1 X N/A				1.00	703.00	23.00	541.31
M AIR DAM, SIDE, FR RH				1.00	19.00	23.00	14.63
M BRACKET, FR BUMPER SIDE, RH BR				1.00	8.00	23.00	6.16
M GARNISH, FR BUMPER, RH MIS				1.00	44.00	23.00	33.88
M GRILLE ASSY, RADIATOR 1 X N/A				1.00	597.00	23.00	459.69
M COVER, FR BUMPER GRILLE BR				1.00	157.00	23.00	120.89
M LAMP ASSY, FOG, FR LH BR				1.00	303.00	23.00	233.31
M FENDER, FR RH BR				1.00	428.00	23.00	329.56
M SHIELD, FR WHEELHOUSE, RH TN				1.00	98.00	23.00	75.46
M WHEEL, DISC CUT				1.00	598.00	23.00	460.46
M EMBLEM ECO APC				1.00	17.00	00.00	17.00

Estimate

Stere (CLKK)

28/12/20, 11:00am

OD- N/A Auth

EXCERS - ?

5 dgs

P/P

Estimate

Stere (LKK)

28/12/20, 11:00am

OD - N/A

EXCERS - ?

5 dys

P/P

Ry B/L spj

Confirm &amp; accepted by

the following:

- To repair or replace/after spray painting
- To display damaged part(s) during resurvey
- Parts price is subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on Net 6,101.41  
427.10  
Total Payable 6,528.51

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.