



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20014517/R1Ktd3q2	
			Date: 18/02/2021	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLJ 3892C
	Policy No.	D20MTPV01016209	Coverage (\$)	0.00
	Claim No.	CMTD2003794/THE	Excess (\$)	500.00
	Assign From	GRACE TEO	Assign Date	28/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	BMW 116D HATCH	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WBA1V72090V725205	Colour	WHITE
	Odometer	63143 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
	L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm
	R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
	L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/12/2020	Inspection Date	29/12/2020
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
	A)THE MARKET VALUE IS S\$73,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	