



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10928/LEE MUN CHUNG (LI MINZHONG) Reg No/Reg Date SFA4832M*ECB1/ 20/08/201 Date In/Mileage / 0 Chassis No KNAF3416MK5049787 Engine No G4FGKH744191 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	28/12/2020/ 10:05	QUD	247 / DonBong	26326		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON RH FRONT FENDER, RH FRONT DOOR, REPAIR RH SIDE SILL PANEL				400 x 1.5			600 1200.00
E PNT88000 TRANSFER RH FRONT DOOR GLASS, DOOR TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL							X 120.00
E PNT98000 PAINT WORK SPRAY RH FRONT FENDER, RH FRONT DOOR, RH SIDE SILL PANEL AND AFFECTED PORTION CLEAR COAT CR5				480' x 2 (CR5 colour)			960 1440.00
M SUNDRY APPLY BODY SEALANT							X 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
M SUNDRY PERFORM RUST PREVENTION							40 80.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
A 20000001 RENEW FRONT UNDERCARRIAGE							? 400.00
M SUNDRY LABOUR RENEW RH FRONT SPORT RIM INCLUDING BALANCING							30.00
M SUNDRY SUNDRIES							20 50.00
M PANEL-FENDER,RH				1.00	430.00	20.00	344.00
M INSULATOR-FENDER RH				1.00	27.00	20.00	21.60
M PANEL ASSY-FRONT DOOR,RH				1.00	1277.00	20.00	1021.60
M BLACK TAPE-FR DR RR,RH				1.00	13.00	20.00	10.40
M LAMP ASSY-HEAD,RH				1.00	2210.00	20.00	1768.00
M WHEEL ASSY-ALUMINIUM				1.00	926.00	20.00	740.80
M GEAR ASSY-STEERING				1.00	770.00	20.00	616.00
M HUB ASSY-FR WHEEL				1.00	436.00	20.00	348.80
M ARM COMPLETE-FR LWR,RH				1.00	286.00	20.00	228.80

Estimate

28/12/20, 11:00am

Steve CLKK

00-NM Aut

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: 00-NM Aut

Estimate

Confirm & accepted byLKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications to be allowed

Authorized signatory and company stamp

DATE :

REMARKS :

7% GST on

Total Payable

Nett

8650.00

8,650.00

605.50

9,255.50

• Supply and delivery of this estimate is valid for 14 days from date of quote. This is a computer generated document, no signature is required.

• Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.