



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LIM SI JIE	Cust No/Name /LIM SI JIE
BLK 82A CIRCUIT ROAD	Reg No/Reg Date SMR8654L / 29/01/202
#12-54	Date In/Mileage / 0
SINGAPORE 371082	Chassis No KNAD6811VL6326726
Contact No Mobile: 96204319	Engine No G3LCKP080193
	Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim EU3 SMOKE BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	28/12/2020/ 12:02		442 / CocoLu	26313			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1600.00
RENEW FRT BUMPER, FRT FENDER RH, FRT DOOR RH					400 X3			1200 180.00
E PNT88000								180.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT98000								1050.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, FRT DOOR RH					350 X3			120.00
B WHEELALIGNMENT								
To Conduct Computerize Full Wheel Alignment								30.00
M SUNDRY								30.00
TRANSFER FRT RIM								120.00
A 90000001								400.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								30.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A 90000001								40.00
RENEW FRT UNDER CARRIAGE								20.00
M SUNDRY								80.00
APPLY SEALANT FOR ACCIDENT PORTION								50.00
M SUNDRY								
Sundry								
M SUNDRY								
APPLY RESEAL FRT NUMBER PLATE FROM LTA								
M SUNDRY								
FRT NUMBER PLATE WITH FRAME								
M COVER-FR BUMPER,LWR					1.00	367.00	00.00	367.00
M COVER-FR BUMPER UPR					1.00	476.00	00.00	476.00
M BRACKET-FR BUMPER SIDE,RH					1.00	13.00	00.00	13.00
M PANEL-FENDER,RH					1.00	401.00	00.00	401.00
M INSULATOR-FENDER RH					1.00	27.00	00.00	27.00
M GUARD ASSY-FRONT WHEEL,RH					1.00	56.00	00.00	56.00
M PANEL ASSY-FRONT DOOR,RH					1.00	858.00	00.00	858.00
M TAPE-FR DR BLACK FRAME RR,RH					1.00	13.00	00.00	13.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
LIM SI JIE BLK 82A CIRCUIT ROAD #12-54 SINGAPORE 371082 Contact No Mobile: 96204319	Cust No/Name /LIM SI JIE Reg No/Reg Date SMR8654L / 29/01/202 Date In/Mileage / 0 Chassis No KNAD6811VL6326726 Engine No G3LCKP080193 Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF Colour/Trim EU3 SMOKE BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	28/12/2020/ 12:02		442 / Cocolu	26313			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BLACK TAPE-FR DR FRAME UPR,RH	✓ REC			1.00	13.00	00.00	13.00
M	MOULDING ASSY-SIDE SILL,RH	X			1.00	248.00	00.00	248.00
M	WHEEL ASSY-ALUMINIUM	CUT			1.00	790.00	00.00	790.00
M	HUB ASSY-FR WHEEL	✓ REC			1.00	145.00	00.00	145.00
M	BEARING-FRONT WHEEL HUB	✓ Jammed			1.00	131.00	00.00	131.00
M	KNUCKLE-FRONT AXLE,RH	?			1.00	340.00	00.00	340.00
M	LINK-STABILIZER	?			1.00	94.00	00.00	94.00
M	GEAR ASSY-STEERING	?			1.00	923.00	00.00	923.00
M	STRUT ASSY-FR,RH	?			1.00	269.00	00.00	269.00

Estimate

OD- NM AL
 Excess - ?
 P/P
 Ry Bal sm
 6 chgs
 Steve CLKK)
 28/12/20, 12:00pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirmed & accepted by

Date:

7% GST on Nett 8,884.00
 8884.00 621.88
 Total Payable 9,505.88

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.