



Not Admitted  
dln

1/5 \$1700  
3 days

Take the Attorney  
28/12/20



陳林摩喙私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel: 68585151 (24 Hours) Fax: 68580877

GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SCG50H  
Date of Accident : 26 December 2020

Miss Chew Xin Ni

Date : 28 December 2020

Estimate To Repair SDW9078Z - Honda Jazz 1.3 CVT (A)

Chassis No : JHMGK3850KS218164

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	n/s front fender <i>Badly</i>	
02	1 pc	n/s front fender inner cowling <i>del/rur</i>	\$ 481.40
03	6 ps	n/s front fender inner cowling clips @ \$4.50 <i>neu</i>	\$ 67.20
04	1 pc	n/s front door <i>Badly</i>	\$ 27.00
05	1 pc	n/s front door power window motor <i>11</i>	\$ 872.30
06	1 pc	n/s front door regulator <i>11</i>	\$ 390.60
07	1 pc	n/s front door top hinge <i>11</i>	\$ 238.70
08	1 pc	n/s front door bottom hinge <i>11</i>	\$ 45.80
09	1 pc	n/s front door mirror assy <i>NN</i>	\$ 45.80
10	1 pc	n/s front fender 1/4 glass inner seal <i>11</i>	\$ 637.80
			\$ 36.80
		Less 20 %	\$ 2,843.40
			\$ 568.68
			\$ 2,274.72
<u>SPECIAL NETT ITEMS</u>			
11	1 pc	n/s front fender 1/4 glass sealant <i>11</i>	\$ 40.00
			\$ 40.00
<u>LABOUR &amp; MISC. CHARGES</u>			
01		To remove and refit n/s front fender 1/4 glass.	\$ 11 120.00
02		To transfer of door fittings and perform water seepage test.	\$ 120.00
03		To rust-proofing of the affected areas.	\$ 300.00
04		To check electrical lighting concerned.	\$ 50.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00
06		Putty and spray painting of the affected portion.	\$ 800.00
07		To check steering geometry and computer wheel alignment.	\$ 80.00
			\$ 2,370.00
<b>Total</b>			\$ 4,684.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

2.1447.9  
252  
1158.32  
2148.32  
1718