

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM BEE LENG
24 PAVILION GROVE
SINGAPORE 658616

Contact : 91594979, 91127369

ESTIMATE

Repair Code : CLM15137

Date in : 24/12/2020

Vehicle Num. : SGJ8998H

Model : MERCEDES BENZ E250 AVG (R18 LED)

Chassis/Eng# : WDD2130452A177190/27492030927683

TP Chian.
Veean

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID '9G TRONIC' EMBLEM	1	110.00	✓ 110.00
REAR BOOTLID 'E250' EMBLEM	1	90.00	✓ 90.00
REAR BOOTLID 'LOGO' CLIPS	3	6.50	✓ 19.50
REAR BOOTLID 'LOGO' EMBLEM	1	60.00	✓ 60.00
REAR BOOTLID LOCK STRIKER	1	88.00	+ 88.00
REAR BOOTLID OUTER CHROME MOULDING	1	141.00	✓ 141.00
REAR BOOTLID WEATHER STRIP	1	238.00	+ 238.00
REAR BUMPER	1	1874.00	✓ 1,874.00
REAR BUMPER BRACKET RIVET	30	6.00	50 180.00
REAR BUMPER CENTER BRACKET	1	258.00	✓ 258.00
REAR BUMPER LH ALUMINIUM HEAT SHIELD	1	88.00	+ 88.00
REAR BUMPER LH REFLECTOR	1	170.00	65 ✓ 170.00
REAR BUMPER LOWER BRACKET L/R	2	31.00	+ 62.00
REAR BUMPER LOWER CHROME MOULDING	1	316.00	✓ 316.00
REAR BUMPER LOWER LID	1	675.00	385 ✓ 675.00
REAR BUMPER LOWER SECTION BRACKET	1	43.00	+ 43.00
REAR BUMPER REINFORCEMENT	1	836.00	+ 836.00
REAR BUMPER REVERSE SENSOR	2	234.00	✓ 468.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM BEE LENG
24 PAVILION GROVE
SINGAPORE 658616

Contact : 91594979, 91127369

ESTIMATE

Repair Code : CLM15137

Date in : 24/12/2020

Vehicle Num. : SGJ8998H

Model : MERCEDES BENZ E250 AVG (R18 LED)

Chassis/Eng# : WDD2130452A177190/27492030927683

REAR BUMPER REVERSE SENSOR 'O' RING <i>new</i>	2	18.00	✓	36.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	25.00	✓	100.00
REAR BUMPER SIDE BRACKET L/R <i>LH Right</i>	2	109.00	<i>109</i>	218.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	31.00	✗	62.00
REAR LH EXHAUST CHROME BRACKET <i>new culd</i>	1	54.00	✓	54.00
REAR LH EXHAUST CHROME TAIL PIPE <i>new</i>	1	230.00	✗	230.00
REAR LH TAILLAMP <i>culd</i>	1	736.00	✓	736.00
REAR LH TAILLAMP LOWER BRACKET <i>culd</i>	1	73.00	✓	73.00
REAR LH TAILLAMP SIDE GARNISH <i>new</i>	1	48.00	✗	48.00
Subtotal before discount				7,273.50
Percentage discount 10%				727.35
Sub-total 1				6,546.15
Parts-total				7,273.50

LABOUR

- To reset system after repair works
- To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To remove and reinstall exhaust pipe.

✗ 300.00
✓ 60.00
40 ~~120.00~~
600 ~~900.00~~
✗ ~~100.00~~

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LIM BEE LENG
24 PAVILION GROVE
SINGAPORE 658616

Contact : 91594979, 91127369

ESTIMATE

Repair Code : CLM15137

Date in : 24/12/2020

Vehicle Num. : SGJ8998H

Model : MERCEDES BENZ E250 AVG (R18 LED)

Chassis/Eng# : WDD2130452A177190/27492030927683

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,220.00
Parts & Labour Total	9,493.50

1240
200.00
40.00

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Lj
h/s 29/12/20
04 Days

total: 5690.05
h/s: ASK. ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: