



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 8325T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP LH	NOT NECESSARY	2,650.00	-
1	FRONT HEADLAMP TOP BRACKET LH	NOT NECESSARY	110.00	-
1	FRONT HEADLAMP LOWER BRACKET LH	NOT NECESSARY	110.00	-
1	FRONT BUMPER	CUT	1,880.00	1,215.32
1	FRONT BUMPER LOWER BEAM	NOT NECESSARY	185.00	-
1	FRONT BUMPER FOGLAMP LH	NOT NECESSARY	265.00	-
1	FRONT BUMPER FOGLAMP COVER LH	NOT NECESSARY	145.00	-
1	FRONT BUMPER SIDE RETAINER LH	NOT NECESSARY	65.00	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	535.00	-
1	FRONT FENDER SIGNAL LAMP LH	NOT NECESSARY	188.90	-
1	FRONT FENDER INNER SHIELD LH	NOT NECESSARY	157.60	-
1	FRONT HEADLAMP WASHER NOZZLE	CRACKED	389.40	168.82
1	FRONT HEADLAMP WASHER NOZZLE BRACKET	NO SUCH PARTS	101.00	-
	LESS 5% DISCOUNT		-339.10	-69.21
			6,442.80	1,314.93
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT HEADLAMP CLIPS (SN)	NOT NECESSARY	80.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	50.00
1	FRONT FENDER SEALANT (SN)	NOT NECESSARY	100.00	-
			260.00	50.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH.		1,200.00	200.00
	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED.		1,000.00	300.00
	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGE AREAS AND CHECK FOR PROPER FUNCTION.	NOT NECESSARY	150.00	-
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	100.00	-

Report Ref No. CS/SMO20014541/Uqd3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CLEAR FAULT CODE WITH DIAGNOTIC COMPUTER AND RESET TO BMW SPECIFICATION. }		150.00	30.00
	TO REMOVE AND REPLACE FRONT HEADLAMP LH. }		150.00	-
			2,750.00	530.00
GRAND TOTAL			9,452.80	1,894.93
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,500.00

Report Ref No. CS/SMO20014541/Uqd3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.